HOME REPORT

COPPER BEECHES

ELGIN IV30 8XT



ENERGY PERFORMANCE CERTIFICATE





Energy Performance Certificate (EPC)

Scotland

Dwellings

COPPER BEECHES, ELGIN, IV30 8XT

Dwelling type:	Detached house
Date of assessment:	18 September 2018
Date of certificate:	28 September 2018
Total floor area:	341 m ²
Primary Energy Indicator:	122 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:


2500-1086-0029-5191-1183 RdSAP, existing dwelling Elmhurst Boiler and radiators, oil

You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£5,382	See your recommendations
Over 3 years you could save*	£456	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO₂ emissions



Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band D (68). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (66)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Low energy lighting	£195	£312.00
2 Solar water heating	£4,000 - £6,000	£141.00
3 Solar photovoltaic (PV) panels	£5,000 - £8,000	£825.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	★★★☆	★★★★☆
Roof	Roof room(s), insulated (assumed)	★★★★☆	★★★☆
Floor	Suspended, insulated (assumed)	—	_
Windows	Fully double glazed	****☆	★★★★☆
Main heating	Boiler and radiators, oil	★★★ ☆☆	★★★☆☆
Main heating controls	Time and temperature zone control	****	****
Secondary heating	Room heaters, LPG	—	
Hot water	From main system	★★★☆☆	★★★☆☆
Lighting	Low energy lighting in 7% of fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 31 kg $CO_2/m^2/yr$.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 10 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.1 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

COPPER BEECHES, ELGIN, IV30 8XT 28 September 2018 RRN: 2500-1086-0029-5191-1183

Estimated energy costs for this home

Estimated energy costs for this nome			
	Current energy costs	Potential energy costs	Potential future savings
Heating	£4,185 over 3 years	£4,269 over 3 years	
Hot water	£405 over 3 years	£246 over 3 years	You could
Lighting	£792 over 3 years	£411 over 3 years	save £456
Total	s £5,382	£4,926	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Po	commended measures	Indicative cost	Typical saving	Rating after improvement	
Re	commended measures	indicative cost	per year	Energy	Environment
1	Low energy lighting for all fixed outlets	£195	£104	C 69	D 66
2	Solar water heating	£4,000 - £6,000	£47	C 70	D 68
3	Solar photovoltaic panels, 2.5 kWp	£5,000 - £8,000	£275	C 74	C 71

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

2 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

3 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	23,540	N/A	N/A	N/A
Water heating (kWh per year)	2,851			

COPPER BEECHES, ELGIN, IV30 8XT 28 September 2018 RRN: 2500-1086-0029-5191-1183

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name:	Mr. Michael McDonald EES/009379 D M Hall Chartered Surveyors LLP
Address:	27 High Street Elgin
	IV30 1EE
Phone number:	01343 548501
Email address:	enquiries@dmhall.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

COPPER BEECHES, ELGIN, IV30 8XT 28 September 2018 RRN: 2500-1086-0029-5191-1183

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.





SINGLE SURVEY





survey report on:

Property address	COPPER BEECHES ELGIN IV30 8XT
------------------	-------------------------------------

Customer	Mr M Ramsay

Customer address	Copper Beeches Elgin IV30 8XT
------------------	-------------------------------------

	Prepared by	DM Hall LLP
--	-------------	-------------

Date of inspection	18th September 2018
--------------------	---------------------



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report² will be from information contained in the Report and the generic Mortgage Valuation Report.

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1. <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3. <u>Category 1:</u> No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	Detached two-storey house.
Accommodation	Ground floor: entrance vestibule and hall, lounge, dining room, breakfast room, breakfast kitchen with family area, study, WC, utility room with WC off. First floor: landing, master bedroom, en-suite shower room, three further bedrooms with en- suite shower rooms, bedroom and bathroom.

Gross internal floor area (m²)	335 approximately
Neighbourhood and location	The property is situated within a semi-rural location approximately three miles west of Elgin where a range of local transport, shopping, educational and social facilities are readily available. The property is located within the grounds of a mansion house. There are other residential properties within the vicinity.

Age	Approximately 10 years.

Weather	Overcast with rain showers.
---------	-----------------------------

Chimney stacks	There are no chimney stacks.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	binoculars where appropriate.

Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.

Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.

.

....

If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
Roof is pitched and clad in natural slate. The ridges are formed in tile. Valleys are formed in lead. The bay window projections are also pitched and clad in slate with metal flashings.
Access to the roof space was obtained via ceiling hatches in the main bedroom wardrobe, second bedroom wardrobe and bedroom five.
The roof is of timber frame construction with timber sarking boards. There is underslate felt. Glass wool insulation has been laid between the ceiling joists. The roof spaces could not be accessed due to limited size. These areas have been inspected from the hatches only.

Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	The gutters are of a PVC half round design with PVC round downpipes.

Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of cavity construction with a timber frame load bearing inner leaf round a rough casted concrete blockwork outer leaf. Some stone features have been incorporated externally. There is provision for sub-floor ventilation via air vents at ground level.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	Windows are of a double glazed uPVC type. There are a number of double glazed Velux window units. Timber facings, soffits and fascias around the rear dormer are formed in timber. The front door is of a timber frame paneled design with leaded stained glass glazed inserts. The rear door is of a timber frame and paneled design with glazed insert. There are French windows to the rear at ground and first floor levels which are of a double glazed uPVC type. The rails across the Juliet balconies are formed in metal. There are timber facings above the front door.

External decorations	Visually inspected.
	External timbers are finished in natural wood stain.
Conservatories / porches	None.
Communal areas	None.
Garages and permanent outbuildings	Visually inspected. Integral double car garage of block construction under a pitched and slated roof. The floor is of solid concrete construction. There are dual electric up and over doors. Power and light are installed.

Outside areas and boundaries	Visually inspected.
	There are areas of garden to the front, sides and the rear. Boundaries are defined by beech hedging and post and wire fencing. To the front there is a hard core and chipped driveway and parking area. There are large areas of lawn and a flagstone patio to the rear. A concrete path and ramp provide pedestrian access.

Ceilings	Visually inspected from floor level.
	Ceilings are lined in plasterboard.

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are of timber stud construction with plasterboard finishes.

Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Floors are of suspended timber construction overlaid with chipboard. No access was available to any sub-floor areas due to lack of any known hatch.

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Internal doors are of an oak framed and paneled type. Skirtings and door facings are formed in oak. The stairs are formed in timber with an oak balustrade. The kitchen contains a range of fitted floor and wall mounted units and island unit with integral appliances. Work surfaces are formed in composite, although there is a section of hardwood work surface. There are a number of glazed doors at ground floor level. The utility room contains a range of fitted storage units with a stainless steel sink unit and drainer.

Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	There is a gas fire with balanced flue fitted in the lounge.

Internal decorations	Visually inspected.
	Internal walls are mainly painted throughout, although there are some papered finishes.

Cellars	None.
---------	-------

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains electricity supply. Visible wiring is of PVC coated cabling with 13 amp sockets. Consumer unit and electricity meter are located within the garage.
	There is a central vacuum fitted with points throughout the house and the collection bucket in the garage.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	No mains gas supply. Bottled gas supply for the hob and gas fire in the lounge.


Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Mains water supply. Visible pipework is formed in copper and PVC materials. Each of the ground floor toilets contain a white low level WC and wash hand basin. The main bathroom contains a white suite comprising low level WC wash hand basin, bath and shower cubicle with mixer shower over. The main bedroom en-suite shower room contains a white suite comprising low level WC, dual wash hand basins and shower cubicle with mixer shower over. The other three en-suite shower rooms contain white suites comprising low level WC wash hand basins and shower cubicle with mixer shower over. The other three en-suite shower rooms contain white suites comprising low level WC wash hand basins and shower cubicles with mixer shower over.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	There is a Camray 5 oil fired central heating boiler floor mounted in the garage. This supplies steel panel radiators which are fitted with thermostatic valves. This system also supplies domestic hot water. There is a pre-insulated mega flow hot water tank also in the garage adjacent to the boiler. The central heating system is controlled by a programmer and thermostats in the hall and landing. There are electric underfloor heating tiles in each of the bathroom/shower rooms.

Drainage	Drainage covers etc. were not lifted.
	Neither drains nor drainage systems were tested.
	The seller has advised that drainage is to a private system. The system has not been inspected and condition, legal and environmental issues have not been investigated. For the purposes of the valuation, all are assumed to be satisfactory.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	There is a burglar alarm system fitted. There are smoke detectors fitted to ceilings.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no

defects that will have a material effect on the valuation. The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.
The property was fully furnished, occupied and all floors were covered. My visual inspection of the roof areas was restricted due to limited size of the spaces and insulation material.
I have not disturbed insulation in accordance with health and safety guidelines and furniture, personal effects (particularly in cupboards) and floor coverings have not been moved.
No access available to sub-floor timbers due to lack of any known hatch.
I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purpose of this report have assumed there is no Japanese Knotweed within the boundaries of the property or in neighbouring properties.



2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movement	
Repair category	1
Notes	There is no evidence of any dampness, rot or infestation.

Dampness, rot and infestation	
Repair category	1
Notes	There is no evidence of any dampness, rot or infestation.

Chimney stacks	
Repair category	-
Notes	n/a

Roofing including roof space	
Repair category	1
Notes	No reportable defects.

Rainwater fittings	
Repair category	2
Notes	There is a loose gutter on one of the bay windows to the front. There is some weed growth in guttering which should be removed.

Main walls	
Repair category	2
Notes	There is cracking to render above the French windows of the dining room at the rear of the lounge. Corrosion of the flue guard has caused staining to the external wall.

Windows, external doors and joinery	
Repair category	1
Notes	No reportable defects.

External decorations	
Repair category	2
Notes	There is weathering of external timbers.

Conservatories/porches	
Repair category	-
Notes	n/a

Communal areas	
Repair category	-
Notes	n/a

Garages and permanent outbuildings	
Repair category	1
Notes	No reportable defects.

Outside areas and boundaries	
Repair category	1
Notes	The oil tank and gas bottles sit adjacent to a combustible fence.

Ceilings	
Repair category	1
Notes	There is a damp stain to the ceiling in the hall. This area was dry when tested. This may be as a result of a historic leakage or one which is intermittent. There is a shower room directly above this area which should be monitored for any signs of further deterioration.

Internal walls	
Repair category	1
Notes	No reportable defects.

Floors including sub-floors	
Repair category	1
Notes	There are sections of creaky flooring.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No reportable defects.

Chimney breasts and fireplaces	
Repair category	1
Notes	No visual defects identified. Gas appliances should be serviced annually to ensure they run efficiently and safely.

Internal decorations	
Repair category	2
Notes	There is wear and tear to internal décor in places. The owner intends to have refreshening of the internal décor carried out prior to the sale of the property.

Cellars	
Repair category	-
Notes	n/a

Electricity	
Repair category	1
Notes	No visual defects identified.

Gas	
Repair category	1
Notes	No visual defects identified.

F Water, plumbing and bathroom fittings					
Repair category	2				
Notes	There is mould growth on seals around the bases of some of the shower cubicles. Deterioration to seals can lead to spillage and decay in hidden and unseen areas.				

Heating and hot water				
Repair category	1			
Notes	No visual defects identified. Central heating systems should be serviced annually to ensure they run efficiently and safely.			

Drainage	
Repair category	1
Notes	No visual defects identified.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	-
Roofing including roof space	1
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	1
External decorations	2
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	2
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	2
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes X No
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The property is accessed via a private track. A conveyancer can confirm ownership, access rights and maintenance liabilities for the track. For the purposes of valuation all are assumed to be satisfactory.

Estimated reinstatement cost for insurance purposes

£525,000

Valuation and market comments

£500,000 (FIVE HUNDRED THOUSAND POUNDS).

There has been increased demand from purchasers over the past two years.

Signed	Security Print Code [573382 = 8105] Electronically signed			
Report author	Michael G McDonald			
Company name	DM Hall LLP			
Address	27 High Street, Elgin, IV30 1EE			
Date of report	28th September 2018			

Mortgage Valuation Report



Property Address	
Address Seller's Name Date of Inspection	COPPER BEECHES, ELGIN, IV30 8XT Mr M Ramsay 18th September 2018
Property Details	
Property Type	X House Bungalow Purpose built maisonette Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)
Property Style	X Detached Semi detached Mid terrace End terrace Back to back High rise block Low rise block Other (specify in General Remarks)
Does the surveyor be e.g. local authority, mi	lieve that the property was built for the public sector, Yes X No ilitary, police?
Flats/Maisonettes only	y Floor(s) on which located No. of floors in block Lift provided? Yes No No. of units in block No No No No No
Approximate Year of (
Tenure	
X Absolute Ownership	Leasehold Ground rent £ Unexpired years
Accommodation	
Number of Rooms	4 Living room(s) 5 Bedroom(s) 1 Kitchen(s) 5 Bathroom(s) 2 WC(s) 1 Other (Specify in General remarks)
	cluding garages and outbuildings) 335 m² (Internal) m² (External) /greater than 40%) X Yes No
Garage / Parking / 0	Outbuildings
Single garage Available on site?	X Double garage Parking space No garage / garage space / parking space X Yes No
Permanent outbuilding	gs:
None.	

Mortgage Valuation Report

Construction							
Walls	Brick	Stone	Concrete	X Timber frame	Othe	r (specify in Gen	eral Remarks)
Roof	Tile	X Slate	Asphalt	Felt	Other	r (specify in Gen	eral Remarks)
Special Risks							
Has the property	suffered struc	tural moveme	ent?			Yes	X No
If Yes, is this rece	nt or progres	sive?				Yes	X No
Is there evidence, immediate vicinity	•	ason to antici	pate subsidence	, heave, landslip o	or flood in the	e Yes	X No
If Yes to any of th	e above, prov	vide details in	General Remark	S.			
Service Connec	tions						
Based on visual ir of the supply in G			ces appear to be	non-mains, pleas	se comment	on the type a	nd location
Drainage	Mains	X Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	Mains	X Private	None
Central Heating	X Yes	Partial	None				
Brief description of	of Central Hea	ating:					
Oil fired boiler to	radiators.						
Site							
Apparent legal iss	ues to be ver	ified by the co	nvevancer Plea	ase provide a brie	f description	in General R	emarks
Rights of way	X Shared driv	•		amenities on separate		red service conn	
Ill-defined boundar			ural land included wi			er (specify in Ger	
Location							
Residential suburb	Re	sidential within to	wn / city 🗌 Mixe	d residential / comme	rcial 🗌 Mair	nly commercial	
Commuter village	Re	mote village	Sola	ted rural property	X Othe	er (specify in Ger	neral Remarks)
Planning Issues	S						
Has the property I	been extende	d / converted	/ altered?	Yes X No			
If Yes provide det	ails in Genera	al Remarks.					
Roads							
Made up road	Unmade roa	d Partly	completed new road	Pedestrian a	access only	X Adopted	Unadopted

General Remarks

Other rooms: utility room.

Location: rural area near town.

Generally, the property was found to be in acceptable condition commensurate with age and type. There are some items of general maintenance required. At the time of our inspection the subjects were occupied and generally furnished. We have not carried out an underfloor inspection.

The seller has advised that drainage is to a septic tank. The system has not been inspected and condition, legal, environmental issues have not been investigated.

The property is accessed via a private track. A conveyancer can confirm ownership, access rights and maintenance liabilities for the track. For the purposes of valuation all are assumed to be satisfactory.

For the purposes of the valuation all are assumed to be satisfactory.

Essential Repairs

None apparent.			
Estimated cost of essential repairs £	Retention recommended? Yes	X No	Amount £

Mortgage Valuation Report

Comment on Mortgageability

The property will form suitable security for mortgage purposes at the figure of value outlined below.	
Valuations	
Market value in present condition Market value on completion of essential repairs Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT) Is a reinspection necessary?	£ 500,000 £ £ 525,000 Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis? Is the property in an area where there is a steady demand for rented accommodation of this type?	£ n/a

Declaration Signed Security Print Code [573382 = 8105] Electronically signed by:-Surveyor's name Michael G McDonald Professional qualifications **BLE MRICS** Company name DM Hall LLP Address 27 High Street, Elgin, IV30 1EE Telephone 01343 548501 01343 548501 Fax Report date 28th September 2018

PROPERTY QUESTIONNAIRE





Property Questionnaire

PROPERTY ADDRESS:	COPPER BEECHES ARDONEZEAN ELGÍN MORA/ IV308XT.
SELLER(S):	CLUNY'S ESTIÀTE AGENTS

COMPLETION DATE OF	
PROPERTY QUESTIONNAIRE:	18-9-2018.

PROPERTY QUESTIONNAIRE

NOTE FOR SELLERS

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the Date of Entry for the sale of your house, tell your solicitor or estate agent immediately.

PROPERTY QUESTIONNAIRE Information to be given to prospective buyer(s)	
1. Length of ownership	
How long have you owned the property?	
2. Council Tax	
Which Council Tax band is your property in?	۹.
A B C D E F G H	
3. Parking	
 What are the arrangements for parking at your property? (Please indicate all that apply) ✓ Garage ★ 2 Allocated parking space ✓ Driveway Shared parking On street Resident permit Metered parking Other (please specify): 	

an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)? Desirable is desirable to kr 5. Listed Buildings Js your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)? Yes 6. Alterations / additions / extensions Interest	s/No/ on't now
 Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)? 6. Alterations / additions / extensions 	
 one (i.e. a building recognised and approved as being of special architectural or historical interest)? 6. Alterations / additions / extensions 	
	ś/No
a. (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	s/No
If you have answered yes, please describe the changes which you have made:	

	(ii)	Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	
	be to y lf ye bele	ou have answered yes, the relevant documents will needed by the purchaser and you should give them our solicitor as soon as possible for checking. ou do not have the documents yourself, please note ow who has these documents and your solicitor or ate agent can arrange to obtain them.	
b.	or c	/e you had replacement windows, doors, patio doors double glazing installed in your property? ou have answered yes, please answer the three estions below:	Yes/No
	(i)	Were the replacements the same shape and type as the ones you replaced?	Yes/No
	(ii)	Did this work involve any changes to the window or door openings?	Yes/No N/A
	(iii)	Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):	N/A

	Central heating	
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom). <u>If you have answered yes/partial</u> – what kind of central heating is there?	Yes/ No / Partial
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air.) Fuel off externo the fuel off externo the fuel off externo the fuel of the	
	If you have answered yes, please answer the 3 questions below:	
Э.	When was your central heating system or partial central heating system installed?	
	Do you have a maintenance contract for the central	Voc/MX
2.	Do you have a maintenance contract for the central heating system? <u>If you have answered yes</u> , please give details of the company with which you have a maintenance agreement:	Yes/No
	heating system? <u>If you have answered yes</u> , please give details of the company with which you have a maintenance	Yes/No
2.	heating system? <u>If you have answered yes</u> , please give details of the company with which you have a maintenance	

8.	Energy Performance	Certificate		
	Does your propert Certificate which is le		Energy Performance ars old?	Yes/No
9.	Issues that may have	affected your	property	
a.	Has there been any s damage to your prop			Yes/No
	If you have answered any outstanding insu		nage the subject of	Yes/No
b.	Are you aware of the property?	existence of a	sbestos in your	Yes/No
10	If you have answered	<u>yes</u> , please gi	ve details:	NA
10.		<u>ves</u> , please gi	ve details:	NA
10. a.	If you have answered	vices are conn	ected to your	NA
	If you have answered Services Please tick which ser	vices are conn	ected to your	NA
	If you have answered Services Please tick which ser property and give det	vices are conn ails of the sup	ected to your plier:	NJA
	If you have answered If you have answered Services Please tick which ser property and give det Services Gas / liquid	vices are conn ails of the sup Connected	ected to your plier: Supplier	NJA

	Mains drainage	×c			
		NO			
	Telephone			6.040	
		YES	R(BROAD	Bank
	Cable TV / satellite	ince	Sky		
	Broadband	YES	ong		
	Bioauballu	YES	BT		
b.	Is there a septic tank	system at your	property?		Yes/No
	If you have answered questions below:	<u>ves</u> , please an	swer the tw	o	
c.	Do you have approp from your septic tank getuid NGw Do you have a main	?	-		Yes/No/ Don't Know
d.	Do you have a mair tank?	itenance contra	act for you	r séptic	Yes/Mo
	If you have answere company with which	you have a mai	ntenance co	ontract:	
		TBA.	NANUATE	are	
				00 0	
		0P	- BV60	KOC	
		TBA. 1 GR	- EVEO		
		S	- EVEO ENSR		
		S	- EVEC ENER		
		5	- EVEO ENZR		
		5	- EVEO ENER		
		5	- EVEO ENZR		

11	Responsibilities for Shared or Common Areas	
	Responsibilities for enalise of common Areas	
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	Y es/No / Don't Know
	If you have answered yes, please give details:	
	PRIVATE GOAD TEAgreed VS shared a	orts?
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	Yes/No/ Not applicable
	<u>If you have answered yes</u> , please give details:	
C.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes/No
d.	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?	Yes/No
	<u>If you have answered yes, please give details:</u>	
	Bins Ar ENTERANCE	
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	¥es/No
	If you have answered yes, please give details:	

f.	As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	¥es/No
	<u>If you have answered yes,</u> please give details:	
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property?	¥es/No
	If you have answered yes, please provide the name and address and give details of any deposit held and approximate charges:	
b.	Is there a common buildings insurance policy?	Yes/No/ Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes/No/ Don't know
с.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund.	NIA

13.	Specialist Works	
а.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes/No NONB
	<u>If you have answered yes</u> , please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property	
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? <u>If you have answered yes</u> , please give details	Yes/No NONE
С.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	NA
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write below who has</u> <u>these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	

	Guarantees are held by:					N/A
14.	Guarantees				2	
a.	Are there any guarantees	or w	arrant	ies for any	of the	
(i)	following: Electrical work	No	Yes	Don't	With titl	e Lost
(ii)	Roofing	No	Yes	Know Don't	deeds With titl	e Lost
(iii)	Central heating	No	Yes	Know Don't	deeds With titl	e Lost
(iv)	NHBC	NQ	Yes	know Don't	deeds With titl	e Lost
(v)	Damp course	No	Yes	know Don't	deeds With titl	e Lost
(vi)	Any other work or installations? (for example, cavity wall insulation,	1	Yes	know Don't know	deeds With titl deeds	e Lost
	underpinning, indemnity policy)		STA	NDARD	NHBC	
b.	If you have answered 'yes of the work or installation					

30	*	
C.	Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details:	Yes/No
15.	Boundaries	
	So far as you are aware, has any boundary of your property been moved in the last 10 years? If you have answered yes, please give details:	Yes/No/ Don't Know
16.	Notices that affect your property	
	In the past 3 years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	Yes/No/ Don't know
b.	that affects your property in some other way?	Yes/No/ Don't
c.	that requires you to do any maintenance, repairs or improvements to your property?	know Yes/No/ Don't know

If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.

Declaration by the seller(s)/or other authorised body or person(s):

I / We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :

.....

.....

.....

Date:

DM Hall Offices

Aberdeen 01224 594172

Cumbernauld

01236 618900

01334 844826

01387 254318

01382 873100

Ayr

Cupar

Dumfries

Dundee

Galashiels 01896 752009

Glasgow (North) 01292 286974 0141 332 8615

> Glasgow (South) 0141 636 4141

> > Hamilton 01698 284939

Inverness 01463 241077

Inverurie 01467 624393

Irvine 01294 311070

Kirkcaldy 01592 598200 Livingston 01506 490404

Musselburgh 0131 665 6782

Oban 01631 564225

Paisley 0141 887 7700

Perth 01738 562100

Peterhead 01779 470220

Stirling 01786 475785



Dunfermline 01383 621262

Edinburgh 0131 477 6000

Elgin 01343 548501

Falkirk 01324 628321