

# HARVEY DONALDSON & GIBSON

CHARTERED SURVEYORS

Parent to HomeReportScotland.scot







- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



#### survey report on:

3 di 1 di	
Property address	41 Califer Road, Forres, IV36 1HY
Customer	Mr G Jamieson
Customer address	
Prepared by	Harvey Donaldson And Gibson
Date of inspection	9th January 2020



#### **PART 1 - GENERAL**

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The ultimate holding company of Harvey Donaldson & Gibson is Countrywide plc. In Scotland, Countrywide plc also own Slater Hogg & Howison and Countrywide North. A full list of estate agents owned or under franchise to Countrywide plc is available on request. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information

contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be

researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a two storey mid-terraced house which was originally built for the local authority.
Accommodation	The Accommodation comprises -
	Ground Floor - Entrance Vestibule, Hallway, Living Room and Kitchen.
	First Floor - Landing, Bathroom and Two Bedrooms.
Gross internal floor area (m²)	74
Neighbourhood and location	The property is situated within an established residential area, mostly made up of local authority housing. Surrounding properties are of similar age and character. Usual amenities and transport links are available within a reasonable distance
Age	50 years.
Weather	It was dry and overcast at the time of the inspection.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	The chimneyhead is of brick construction, dressed in lead flashings, where visible from ground level.

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof is pitched, timber framed and covered with concrete interlocking tiles.
	Access to the roof space is via a ceiling hatch located on the landing. Insulation has been laid between and over the joists.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Rainwater discharge is via uPVC gutters and downpipes.
Main walls	Wassella in a second and the second
Main wans	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main external walls are of cavity blockwork construction with facing brick and render externally. There is evidence that cavity wall fill insulation has been installed at some stage.
	Subfloor ventilation was noted in the form of air vents to the front and rear elevation.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows and doors are of a double glazed upvc.
External decorations	Visually inspected.
	External decorations are painted.
Conservatories / porches	Not applicable.
Communal areas	Not applicable.

Garages and permanent outbuildings	Visually inspected.
	There are blockwork stores to the front and rear of the property, both accessed via upvc type doors and form part of the main house structure.
	There is a timber store located in the rear garden under a felt roof. There was no access into the store at the time of the inspection.
Outside areas and boundaries	Visually in spectral
Outside areas and boundaries	Visually inspected.
	There are garden grounds to the front and rear of the property which are suitably bounded by timber fencing.
	The grounds mostly consist of gravel and paved areas. There is an area to the rear of the property which allows for off street parking.
Ceilings	Visually inspected from floor level.
	Ceilings throughout the property are of plasterboard materials.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are lined with plasterboard.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	The ground floor is suspended timber construction.
	The first floor is timber.
Internal joinary and kitchen fittings	Duilé in combanda organista la
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	The internal doors are a mixture of timber panelled, hollow flush faced units and timber with glazed inserts.
	The skirting boards and door surrounds are timber.
	The staircase is timber.
	The kitchen fittings consist of a range of floor and wall mounted

Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	It is understood that a fireplace was an original feature of the building however, the fireplace has been boarded over/bricked up and the surrounds removed and is no longer operational. It is assumed that any unused flues are suitably vented.
Internal decorations	Visually inspected.
internal decorations	The ceilings are painted and the walls are painted and papered.
	The internal joinery is mostly painted.
	The kitchen is finished with tiles and the bathroom is finished with
	tiles and wetwall.
Cellars	Not applicable.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains electricity is installed, however the electrics were not on at the time of our inspection.
	The meter and consumer unit are located in the cupboard under the stairs. The system appears to be of a 13 amp type and design. The switch and socket outlets are plastic and chrome and the wiring is sheathed with PVC, where visible.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Gas is supplied from the mains. The meter is located in an external meter box located to the front of the property.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Water is supplied from the mains.
	The bathroom contains a bath with an electric shower over, wash hand basin and w.c.
	The visible pipework is a mixture of copper and plastic.

Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.	
	No tests whatsoever were carried out to the system or appliances.	
	The property is centrally heated by means of a gas fired system, comprising a condensing combination boiler located in the first bedroom cupboard. Heating to the rooms is provided by water filled radiators. The system is of a type designed to provide instantaneous hot water upon demand.	
Drainage	Drainage covers etc were not lifted.	
	Neither drains nor drainage systems were tested.	
	Mains drainage is understood to be connected.	
Fire, smoke and burglar alarms	Visually inspected.	
	No tests whatsoever were carried out to the system or appliances.	
	appriarios:	

#### Any additional limits to inspection

#### For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

This report does not constitute a full and detailed description of the property and a structural investigation was not carried out. No inspection was undertaken of woodwork or other parts of the structure which are covered, unexposed or otherwise inaccessible and as a result no guarantee can be given that such parts of the structure are free from rot, beetle or other defects.

The external building fabric has been inspected from ground level only from the subjects grounds and where possible from adjoining public property. Exposure work has not been carried out.

It was dry on the date of inspection. Leakage and water penetration within roof spaces, around chimney breasts, window openings, etc are sometimes only visible during or immediately after, adverse weather conditions.

No sub-floor inspection was possible due to no apparent means of access.

The roof space inspection was limited to a head and shoulders style basis only, due to the presence of insulation material being laid between and over the ceiling joists.

There was no access into the timber store at the time of the inspection.

There is a build up of moss growth on the roof covering which restricted our inspection of the roof surface.

No close inspection was possible to enclosed areas beneath and around washing appliances and sanitary fittings.

#### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3 Chimney head
- 4 Flashing
- 5) Ridge ventilation
- 6 Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- 12) Sarking
- 13) Roof felt
- (14) Trusses
- (15) Collar
- 16 Insulation
- 17) Parapet gutter
- (18) Eaves guttering
- (19) Rainwater downpipe
- 20) Verge boards/skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- (25) Window pointing
- 6) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- (33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40 Hot water tank

#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	No obvious significant structural movement noted, on the basis of a single inspection.

Dampness, rot and infestation	
Repair category	1
Notes	An electronic moisture meter was used to measure levels of dampness, at random locations, to lower wall surfaces and floors, where accessible and without moving furniture or lifting floor coverings, if present. No obvious significant dampness, timber decay or infestation noted, within the limitations imposed on the inspection.

Chimney stacks	
Repair category	1
Notes	From a ground level inspection, no obvious significant defects were noted to the chimneyhead.
	Chimneys can be vulnerable to defects and should be regularly maintained.

Roofing including roof space	
Repair category	2
Notes	Roof tiling, where viewed from ground level, appears to have been laid to generally even courses however, an accumulation of moss growth was noted on the tiling. Vegetation of this type has been known to retain moisture which could subsequently be directed back into the building fabric.  The manufacturers of concrete roof tiles expect that they will have a life span of around 40-50 years. This should be taken into consideration having regard to the age of this property.

Rainwater fittings	
Repair category	1
Notes	No significant disrepair was noted to the rainwater goods. It will however be appreciated that the inspection was carried out during dry weather conditions. Sometimes defects in rainwater goods are only apparent during, or after heavy rainfall.

Main walls	
Repair category	1
Notes	No obvious significant defects were noted to the accessible wall surfaces, allowing for age and weathering.

Windows, external doors and joinery	
Repair category	2
Notes	A double glazed window unit to the kitchen has failed, as a result of defective seals, allowing condensation to build between the panes.  No obvious significant defects noted to the other windows or doors, although the windows are not modern and the life expectancy of same should be fully appreciated.

External decorations	
Repair category	1
Notes	No obvious significant defects noted to the external decorations allowing for areas of weathering and deterioration to the ironmongery.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	1
Notes	No obvious significant defects noted to the stores.  Externally, no obvious significant defects were noted to the timber store. However it should be noted that mineral felt has a limited life expectancy and has been known to fail after a short period of time, and life expectancy cannot, therefore, be guaranteed.

Outside areas and boundaries	
Repair category	1
Notes	General maintenance should be envisaged to the outside areas as parts of the timber fencing are weathered and the rear gate proved difficult to open. The paving is also cracked and uneven in places.

Ceilings	
Repair category	1
Notes	No obvious significant defects were noted to the ceiling surfaces, allowing for minor blemishes.

Internal walls	
Repair category	1
Notes	No obvious significant defects were noted to the internal walls, allowing for minor evidence of unevenness and impact damage.

Floors including sub-floors	
Repair category	1
Notes	No obvious significant defects were noted to the flooring, within the limitations imposed by fully fitted floor coverings.
	The carpet to the second bedroom has been removed, leaving just the underlay.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No obvious significant defects were noted to the internal joinery or kitchen fittings allowing for areas of wear and tear.
	It should be confirmed that the glass door contains safety glass to comply with current regulations.

Chimney breasts and fireplaces	
Repair category	1
Notes	All blocked chimneys/fireplaces require to be vented in order to avoid a build up of condensation dampness.

Internal decorations	
Repair category	1
Notes	No obvious significant defects were noted to the internal decoration, allowing for areas of wear and tear.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	1
Notes	It is likely that only the most recently rewired properties will have electrical installations that fully comply with current regulations. The installation in this property has been tested with the next test due in 2024.  It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check.

<b>d</b> Gas	
Repair category	1
Notes	No obvious significant defects noted. All gas appliances should be tested and thereafter regularly maintained by a Gas Safe registered contractor.

T- Water, plumbing and bathroom fittings	
Repair category	1
Notes	No obvious significant defects noted to the accessible plumbing or sanitary fittings.
	Given the presence of the shower mounted over the bath, it is essential that all wall linings, tile grout, seals, etc are maintained in good condition. Failure to do so can lead to concealed defects behind wall finishes, and below the bath. As the bath is boxed in, it will be appreciated that it is not possible to comment on concealed locations.

Heating and hot water	
Repair category	1
Notes	No obvious significant defects were noted to the heating system or hot water system, although these have not been tested.  It is recommended good practice that gas boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.

Drainage	
Repair category	1
Notes  No obvious significant defects were noted to the drainage system, within the limitations of the inspection.	

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	2
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	2
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

#### Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground floor
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes No X
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The tenure is understood to be Outright Ownership.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

The road and footpaths pertaining to the property are made up and assumed adopted by the local authority.

The property is located in an area affected by historic flooding. As far as we are aware the property has not been affected by flooding and Forres have completed a flood alleviation works. Therefore the valuation assumes that insurance can be obtained on normal terms.

It appears that cavity wall insulation has been installed at some time in the past and, if applicable, any guarantees of works should be transferred with the Title Documents at the point of sale.

Estimated reinstatement cost for insi	irance nurnoses
	uranice purposes.

£125,000 (One hundred and twenty five thousand pounds).

#### Valuation and market comments

We are of the opinion that the current open market value of the property, in the condition found at the time of our inspection, and assuming full vacant possession on 9 January 2020 can be fairly stated in the sum of:

£95,000 (Ninety five thousand pounds sterling).

Signed	Security Print Code [379737 = 6275]O Electronically signed
Report author	India Hill
Company name	Harvey Donaldson And Gibson
Address	Park House Business Centre, South Street, Elgin, IV30 1JB

Date of report	9th January 2020



Property Address	
Address Seller's Name Date of Inspection	41 Califer Road, Forres, IV36 1HY Mr G Jamieson 9th January 2020
Property Details	
Property Type	X House       Bungalow       Purpose built maisonette       Converted maisonette         Purpose built flat       Converted flat       Tenement flat       Flat over non-residential use         Other (specify in General Remarks)
Property Style	□ Detached       □ Semi detached       ▼ Mid terrace       □ End terrace         □ Back to back       □ High rise block       □ Low rise block       □ Other (specify in General Remarks)
Does the surveyor bell e.g. local authority, miles	lieve that the property was built for the public sector, X Yes No Ilitary, police?
Flats/Maisonettes only	
Approximate Year of 0	
Tenure	
X Absolute Ownership	Leasehold Ground rent £ Unexpired years
Accommodation	
Number of Rooms	1     Living room(s)     2     Bedroom(s)     1     Kitchen(s)       1     Bathroom(s)     0     WC(s)     0     Other (Specify in General remarks)
Gross Floor Area (exc	cluding garages and outbuildings) 74 m² (Internal) 85 m² (External)
Residential Element (	greater than 40%) X Yes No
Garage / Parking / 0	Dutbuildings
Single garage Available on site?	□ Double garage       X       Parking space       □ No garage / garage space / parking space         X       Yes       □ No
Permanent outbuilding	gs:
Timber store, Block	store.

Construction							
Walls	X Brick	Ctono	Congrete	Timber frame	Othor	(aposify in Can	oral Ramarka)
Roof	X Brick X Tile	Stone Slate	Concrete Asphalt	☐ Timber frame ☐ Felt	_	(specify in Gen (specify in Gen	
11001	7 1110	Glate	Плорник			(opeony in Cen	oral Romano,
Special Risks							
Has the property su	uffered struc	tural moveme	nt?			Yes	X No
If Yes, is this recen	t or progress	sive?				Yes	No
Is there evidence, himmediate vicinity?		ason to anticip	pate subsidence	, heave, landslip o	r flood in the	X Yes	No
If Yes to any of the	above, prov	ide details in (	General Remark	S.			
Service Connect	ion						
Based on visual insof the supply in Ge	spection only	. If any servic	es appear to be	non-mains, please	e comment or	n the type ar	nd location
	X Mains	Private	None	Water	X Mains	Private	None
_	X Mains	Private	None	Gas	X Mains	Private	None
-	X Yes	Partial	None				
Brief description of	Control Hoo	ting:					
Heating fuel: Gas Heating type: Rad		ung.					
Site							
Apparent legal issu	os to bo vor	find by the co	nyovancor Plaa	co provido a briof	description in	Conoral Pa	omarke
Rights of way	Shared driv	-	_ <i>*</i>	amenities on separate	·	ed service conn	
Ill-defined boundarie	_	'	Garage or other ural land included with				neral Remarks)
III delined boundarie			ardi laria irioladea Wi	an property		(opcony in oci	nordi Romano,
Location							
X Residential suburb	Res	sidential within to	wn / city Mixe	d residential / commer	cial Mainly	y commercial	
Commuter village	Rer	note village	Isola	ted rural property	Other	(specify in Ger	neral Remarks)
Planning Issues							
Has the property be	een extende	d / converted /	/ altered?	res X No			
If Yes provide deta	ils in Genera	l Remarks.					
Roads							
X Made up road	Unmade roa	d Partly o	completed new road	Pedestrian ad	ccess only	Adopted	Unadopted

General Remarks
The property is situated in a residential area of Forres amongst properties of similar age and type of construction, within reasonable proximity to local amenities.
The general condition of the property appears consistent with age and type of construction, but some works of repair and maintenance are required.
The property is located in an area affected by historic flooding. As far as we are aware the property has not been affected by flooding and Forres have completed a flood alleviation works. Therefore the valuation assumes that insurance can be obtained on normal terms.
It appears that cavity wall insulation has been installed at some time in the past and, if applicable, any guarantees of works should be transferred with the Title Documents at the point of sale.
Essential Repairs
None apparent within the limitations of our inspection.
Estimated cost of essential repairs £ Retention recommended? YesX No Amount £

Comment on Mortgageability					
The property affords adequate security for loan purposes based on the valuation figure, subject to individual lender's criteria.					
Valuations					
Market value in present condition  Market value on completion of essential repairs  Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)  Is a reinspection necessary?  Buy To Let Cases					
What is the reasonable rangementh Short Assured Tenar	ge of monthly rental income for the property assuming a letting on a 6 ncv basis?	£			
	where there is a steady demand for rented accommodation of this type?	Yes No			
Declaration					
Signed Surveyor's name Professional qualifications Company name	Security Print Code [379737 = 6275]O Electronically signed by:- India Hill AssocRICS Harvey Donaldson And Gibson				
Park House Business Centre, South Street, Elgin, IV30 1JB  O1343547844  O203 880 9193  Report date  9th January 2020					

### **Energy Performance Certificate (EPC)**

Dwellings

### **Scotland**

#### 41 CALIFER ROAD, FORRES, IV36 1HY

Dwelling type:Mid-terrace houseDate of assessment:09 January 2020Date of certificate:09 January 2020

Total floor area: 74 m<sup>2</sup>

Primary Energy Indicator: 207 kWh/m²/year

**Reference number:** 0110-2571-8190-2800-1131 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

#### You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£1,941	See your recommendations	
Over 3 years you could save*	£360	report for more information	

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (72)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



#### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (72)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Floor insulation (suspended floor)	£800 - £1,200	£159.00
2 Low energy lighting	£30	£117.00
3 Solar water heating	£4,000 - £6,000	£81.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, filled cavity	<b>★★★☆☆</b>	<b>★★★☆☆</b>
Roof	Pitched, 150 mm loft insulation	<b>★★★</b> ☆	<b>★★★★</b> ☆
Floor	Suspended, no insulation (assumed)	_	_
Windows	Fully double glazed	<b>★★★☆☆</b>	<b>★★★☆☆</b>
Main heating	Boiler and radiators, mains gas	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Main heating controls	Programmer, room thermostat and TRVs	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Secondary heating	None	_	_
Hot water	From main system	***	<b>★★★★☆</b>
Lighting	Low energy lighting in 25% of fixed outlets	***	***

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 36 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.7 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

#### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£1,383 over 3 years	£1,239 over 3 years	
Hot water	£246 over 3 years	£165 over 3 years	You could
Lighting	£312 over 3 years	£177 over 3 years	save £360
Totals	£1,941	£1,581	over 3 years


These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement		
		Indicative cost	per year	Energy	Environment	
1	Floor insulation (suspended floor)	£800 - £1,200	£53	C 74	C 75	
2	Low energy lighting for all fixed outlets	£30	£39	C 76	C 76	
3	Solar water heating	£4,000 - £6,000	£27	C 77	C 78	
4	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£300	B 88	B 88	

#### Choosing the right improvement package





#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

#### 2 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

#### 3 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

#### 4 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

#### Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	7,735	(274)	N/A	N/A
Water heating (kWh per year)	1,842			

#### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Miss India Hill Assessor membership number: EES/019913

Company name/trading name: Harvey Donaldson & Gibson Chartered Surveyors

Address: The Park House Business Centre

South Street Elgin IV30 1JB

Phone number: 01343547844

Email address: frances.wilson@hdg.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

#### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT





Property address	41 califer road pilmuir forres  morayshire IV361HY
Seller(s)	Gareth Jamieson
Completion date of property questionnaire	08/01/20





#### **Note for sellers**

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

#### Information to be given to prospective buyer(s)

1.	Length of ownership			
	How long have you owned the property? 3			
2.	Council tax			
	Which Council Tax band is your property in? (Please tick)			
	A⊠ B□ C□ D□ E□ F□ G□ H□			
3.	Parking			
	What are the arrangements for parking at your property? (Please tick all that apply)			
	● Garage □			
	Allocated parking space			
	• Driveway ⊠			
	Shared parking			
	● On street ⊠			
	Resident permit			
	Metered parking			
	Other (please specify):			
4.	Conservation area			
	Is your property in a designated Conservation Area (that is an area of	Yes		
	special architectural or historical interest, the character or	No	$\boxtimes$	
	appearance of which it is desirable to preserve or enhance)?	Don't know		
5.	Listed buildings			
	Is your property a Listed Building, or contained within one			
	(that is a building recognised and approved as being of special	Yes		
	architectural or historical interest)?	No		
6.	Alterations/additions/extensions			
a.	(i) During your time in the property, have you carried out any	Voc		
	structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes No	$\square$	
	ı bi uvision vi an exhabanksnower rudin, tunet, ul bedi udin!	110	لحا	



	If you have answered yes, please describe below the changes which you have made:		
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	Yes No	
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below:	Yes   No	
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes   No	
	(ii) Did this work involve any changes to the window or door openings?	Yes No	
	(iii) Please describe the changes made to the windows doors, or approximate dates when the work was completed):  Please give any guarantees which you received for this work to ye state agent.		
7.	Central heating		
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).	Yes No Partial	
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).  If you have answered yes, please answer the three questions below:	gas	
	i) When was your central heating system or partial central heating system installed?	2014	



	(ii) Do you have a maintenance contract for the central heating system?	Yes No	
	If you have answered yes, please give details of the company with which you have a maintenance contract:		
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).		
8.	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes No	$\square$
9.	Issues that may have affected your property		
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes No	
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes No	
b.	Are you aware of the existence of asbestos in your property?  If you have answered yes, please give details:	Yes No	
	ii you nave answered yes, please give details.	110	<b>12-3</b>



10.	Services				
a. Please tick which services are connected to your property and give details of the supplier:					
Servi	ces	Connected	Supplier		
Gas	r liquid petroleum gas	yes			
	r mains or private supply	yes			
Elect	ricity	yes			
Main	s drainage	yes			
Telep	hone	yes			
Cable	e TV or satellite	yes			
Broad	dband	yes			
			<u> </u>		
b.	Is there a septic tank system at your property? If you have answered yes, please answer the two questions below:			Yes No	
	(i) Do you have appropriate consents for the discharge from your septic tank?			Yes No Don't know	
	(ii) Do you have a mainten If you have answered yes with which you have a ma	Yes No			
11.	Responsibilities for share				
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?  If you have answered yes, please give details:			Yes No Don't know	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?  If you have answered yes, please give details:			Yes No Don't know	
C.	Has there been any major roof during the time you ha	epair or replacement of any p ve owned the property?	art of the	Yes No	



d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?	Yes No	
	If you have answered yes, please give details:		
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?  If you have answered yes, please give details:	Yes No	
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)  If you have answered yes, please give details:	Yes No	
12.	Charges associated with your property		
a.	Is there a factor or property manager for your property?  If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	Yes No	
b.	Is there a common buildings insurance policy?  If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes No Don't know	
C.	Please give details of any other charges you have to pay on a regular upkeep of common areas or repair works, for example to a resident maintenance or stair fund.		r
13.	Specialist works		
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?  If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	Yes No	
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?  If you have answered yes, please give details:	Yes No	



C.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?  If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself, your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.  Guarantees are held by:			r . You	Yes No	
14.	Guarantees					
a.	Are there any guarantees or warranties fo	r any of th	ne followi	ng:		
		No	Yes	Don't know	With title deeds	Lost
(i)	Electrical work	$\boxtimes$				
(ii)	Roofing	$\boxtimes$				
(iii)	Central heating	$\boxtimes$				
(iv)	National House Building Council (NHBC)	$\boxtimes$				
(v)	Damp course	$\boxtimes$				
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)					
b.	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):					
C.	Are there any outstanding claims under any of the guarantees listed above?				Yes No	
	If you have answered yes, please give details:					
15.	Boundaries					
	So far as you are aware, has any boundary of your property been moved in the last 10 years?  If you have answered yes, please give details:			been	Yes No Don't know	
16.	Notices that affect your property					

Yes

Yes

No

No

 $\boxtimes$ 

In the past three years have you ever received a notice:

that affects your property in some other way?

planning application?

a.

b.

advising that the owner of a neighbouring property has made a



c.	that requires you to do any maintenance, repairs or improvements to your property?	Yes No	$\square$
	If you have answered yes to any of a-c above, please give the no solicitor or estate agent, including any notices which arrive at an date of entry of the purchaser of your property.		

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s): Gareth Jamieson

Date: 8/1/20



