HOME REPORT

8 LADY MARGARET DRIVE LHANBRYDE ELGIN IV30 8PX



ENERGY PERFORMANCE CERTIFICATE





Energy Performance Certificate (EPC)

Scotland

Dwellings

8 LADY MARGARET DRIVE, LHANBRYDE, ELGIN, IV30 8PX

Dwelling type:	Detached house
Date of assessment:	03 September 2018
Date of certificate:	05 September 2018
Total floor area:	129 m ²
Primary Energy Indicator:	138 kWh/m²/year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:


0110-2127-4110-9408-8755 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£2,901	See your recommendations
Over 3 years you could save*	£282	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO₂ emissions



Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band B (82). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (80)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Floor insulation (suspended floor)	£800 - £1,200	£189.00	\bigcirc
2 Low energy lighting	£35	£93.00	

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

8 LADY MARGARET DRIVE, LHANBRYDE, ELGIN, IV30 8PX 05 September 2018 RRN: 0110-2127-4110-9408-8755

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, filled cavity Cavity wall, filled cavity and internal insulation	★★★☆☆ ★★★★☆	★★★☆☆ ★★★★☆
Roof	Pitched, 150 mm loft insulation Roof room(s), insulated (assumed)	***☆ ****☆	★★★★☆ ★★★★☆
Floor	Suspended, no insulation (assumed) Suspended, insulated		
Windows	Fully double glazed	★★★☆	★★★★☆
Main heating	Boiler and radiators, mains gas	★★★★ ☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★ ☆	★★★★☆
Secondary heating	Room heaters, wood logs	—	_
Hot water	From main system	****	★★★★☆
Lighting	Low energy lighting in 53% of fixed outlets	****	★★★★☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 22 kg $CO_2/m^2/yr$.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.8 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

8 LADY MARGARET DRIVE, LHANBRYDE, ELGIN, IV30 8PX 05 September 2018 RRN: 0110-2127-4110-9408-8755

Estimated energy of	osts for this home		
	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,271 over 3 years	£2,097 over 3 years	
Hot water	£288 over 3 years	£288 over 3 years	You could
Lighting	£342 over 3 years	£234 over 3 years	save £282
Total	s £2,901	£2,619	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

De	commended measures	Indicative cost	Typical saving	Rating after improvement		Green
Re	commended measures	indicative cost	per year	Energy	Environment	Deal
1	Floor insulation (suspended floor)	£800 - £1,200	£63	B 83	B 82	
2	Low energy lighting for all fixed outlets	£35	£31	B 84	B 83	

Measures which have a green deal tick \bigcirc are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick \bigcirc may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

2 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present:

- Biomass secondary heating
- Solar photovoltaics

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	13,621	(259)	N/A	N/A
Water heating (kWh per year)	2,158			

8 LADY MARGARET DRIVE, LHANBRYDE, ELGIN, IV30 8PX 05 September 2018 RRN: 0110-2127-4110-9408-8755

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name:	Mr. David Cruickshank EES/012072 D M Hall Chartered Surveyors LLP
Address:	17 Corstorphine Road Edinburgh
	EH12 6ĎD
Phone number:	0131 477 6006
Email address:	enquiries@dmhall.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.



SINGLE SURVEY





survey report on:

Property address	8 LADY MARGARET DRIVE LHANBRYDE ELGIN IV30 8PX
------------------	---

Customer MS CATRIONA SMITH

Customer address	8 LADY MARGARET DRIVE LHANBRYDE ELGIN IV30 8PX
------------------	---

Prepared by	DM Hall LLP

Date of inspection	3rd September 2018
--------------------	--------------------



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

8 LADY MARGARET DRIVE, LHANBRYDE, ELGIN, IV30 8PX 3rd September 2018 HP560278

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:-

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report² will be from information contained in the Report and the generic Mortgage Valuation Report.

8 LADY MARGARET DRIVE, LHANBRYDE, ELGIN, IV30 8PX 3rd September 2018 HP560278

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1. <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2. <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3. <u>Category 1:</u> No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value, the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	A detached house.
Accommodation	Ground floor: hall, living room, kitchen/dining room, two bedrooms, shower room/W.C and porch. Upper floor: landing providing access to two bedrooms and a bathroom /W.C.

Gross internal floor area (m²) 129 approximately.

Neighbourhood and location	The property is situated within an established residential street comprising part of Lhanbryde village. Local amenities and facilities are available in close proximity.
----------------------------	--

Age	53 years approximately.
Weather	It was dry and sunny after a prolonged period of mainly similar weather.

Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	There is one chimney which is constructed from rendered concrete blocks, flashings are of lead.

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.

If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
The roof is pitched and clad with small clay tiles. Access was gained to the eaves at the upper floor level through hatches at the front and rear of the property. It is evident that the roof is timber framed with timber sarkings and assumed underfelt beneath the tiles. Glasswool insulation has been laid between the joists, on the vertical stud walls and sloping ceiling.

Main walls	Visually inspected with the aid of binoculars where
	Rainwater fittings comprise half round gutters and round downpipes in a mixture of cast iron and PVC.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.

Foundations and concealed parts were not exposed or inspected.
The main outerwalls are of cavity concrete block construction with a rendered external finish. The basecourse is of brick and incorporates subfloor ventilation grills. Cavity wall insulation has been injected to improve thermal efficiency, with further internal insulation internally on the walls around the living room and kitchen/dining room.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	Windows: windows comprise uPVC framed double glazed casements with Velux style roof lights used at the upper floor level.
	External doors: the front door is of UPVC while the rear door is uPVC and fully double glazed. In addition, there is a further wooden door leading to the garage. The living room has uPVC framed double glazed patio doors which provide access to the back garden patio.
	Other joinery finishes: The fascias and soffits to the eaves are lined in softwood.

External decorations	Visually inspected. The external walls, woodwork and cast iron rainwater fittings are painted.
Conservatories / porches	Visually inspected.
	There is an attached porch to the rear of the property which would appear to be of rendered concrete block construction under the main pitched and tiled roof.

Communal areas	Circulation areas visually inspected.
	There are no communal areas.

Garages and permanent outbuildings	Visually inspected.
	There is an attached single tandem garage which is of rendered concrete block construction under a flat profiled sheet steel roof. There is electric light and power. There is a metal up and over car door to the front with PVC door and uPVC double glazed window to the rear.

Outside areas and boundaries	Visually inspected.
	There are private garden areas to the front and rear of the house, with paths at the sides. gardens are mainly laid out to lawns and borders, with a paved patio at the rear. There is a chipped drive leading to the garage. Boundaries are defined by block walls at the front and wooden fences at the rear.

Ceilings	Visually inspected from floor level.
	Ceilings are lined in plasterboard.
Internal walls	Visually inspected from floor level.

Using a moisture meter, walls were randomly tested for
dampness where considered appropriate.

Internal walls are mainly lined in plasterboard.

Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Flooring throughout the property is of suspended timber which is

	overlaid with tongue and groove boarding or an equivalent material. The floor beneath the living room and kitchen is insulated.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Kitchen: the kitchen is fitted with a range of laminated cabinets and manufactured stone worktops.
	Staircase: there is a timber staircase with banister/handrail.
	Doors: internal doors are mainly wooden some of which are partly glazed.
	Other joinery finishes: other joinery finishes are wooden.

Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	There is a wood burning stove in the living room which sits on a raised slate hearth.

Internal decorations	Visually inspected.
	Walls and ceilings are mainly painted and papered.
Cellars	Visually inspected where there was a safe and purpose-built

Cellars	Visually inspected where there was a safe and purpose-built access.
	There are no cellars.

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. There is a mains electricity supply. The meter and consumer unit are located within a cupboard in the hall. Wiring, where visible is PVC sheathed and 13 amp sockets have been installed throughout the property.
-------------	--

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	There is a mains gas supply, the meter is concealed within an external box on the west gable end.

Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	There is a mains water supply. Plumbing where visible is in copper and plastic. There is a stainless steel sink in the kitchen.
	The shower room at the ground floor level comprises three white fittings with a wall mounted mixer shower within the shower compartment.
	The bathroom at the upper floor level comprises three white fittings.


Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	There is gas central heating working from a wall mounted Worcester Greenstar combination boiler which is located within a cupboard in an upper floor bedroom. The boiler provides instantaneous hot water as well as central heating via steel panelled radiators which are distributed throughout the property. There is a wood burning stove in the living room as an alternative source of heat.

Drainage	Drainage covers etc. were not lifted.
	Neither drains nor drainage systems were tested.
	Drainage is to the public sewer.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	There are smoke detectors mounted on the hall and landing ceiling with heat detectors on the living room and kitchen ceilings.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general

condition and standard of maintenance.
At the time of inspection the property was occupied, fully furnished with all floors covered. My inspection of the roof spaces was restricted top what was visible from hatches in the eaves. The subfloor area was not accessed.
When visually inspecting the property I have not disturbed insulation in accordance with Health and Safety Guidelines and furniture, personal effects (particularly in cupboards) and floor coverings have not been moved.
I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purpose of this report have assumed there is no Japanese Knotweed within the boundaries of the property or in neighbouring properties.



2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	

Structural movement	
Repair category	1
Notes	No evidence of movement was noted.

Dampness, rot and infestation	
Repair category	1
Notes	No dampness rot or infestation noted.

Chimney stacks	
Repair category	1
Notes	No defects evident from a ground level inspection.

Roofing including roof space	
Repair category	2
Notes	The roof is clad with old/original materials. There is some moss growth on the roof tiles. Concrete tiles are typically guaranteed for thirty years but have a reasonable life expectation of around fifty/sixty years according to the BRE. Life expectancy will often depend on weathering and damage from the prevailing weather. A roofing contractor will be able to advise on life expectancy and repair/replacement costs.

Rainwater fittings	
Repair category	1
Notes	There is one broken joint at the front of the property, the owner has advised that this will be rectified prior to marketing the house.

Main walls	
Repair category	1
Notes	No reportable defects noted.

Windows, external doors and joinery	
Repair category	1
Notes	No reportable defects noted.

External decorations	
Repair category	1
Notes	No reportable defects noted.

Conservatories/porches	
Repair category	1
Notes	No reportable defects noted.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	1
Notes	No reportable defects noted.

Outside areas and boundaries	
Repair category	1
Notes	No reportable defects noted.

Ceilings	
Repair category	1
Notes	No reportable defects noted.

Internal walls	
Repair category	1
Notes	No reportable defects noted.

Floors including sub-floors	
Repair category	1
Notes	No reportable defects noted.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No reportable defects noted.

Chimney breasts and fireplaces	
Repair category	1
Notes	No visible defects identified. Solid fuel stoves and flues should be regularly checked and swept to ensure they burn safely and efficiently.

Internal decorations				
Repair category	1			
Notes	No reportable defects noted.			

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	1
Notes	No visible defects identified.

Gas	
Repair category	1
Notes	No visible defects identified.

F Water, plumbing and bathroom fittings				
Repair category	1			
Notes	No evidence of leakage was noted from the plumbing.			

Heating and hot water				
Repair category	1			
Notes	No visible defects identified. Annual central heating checks should ensure efficient usage.			

Drainage	
Repair category	1
Notes	No reportable defects noted.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1			
Dampness, rot and infestation	1			
Chimney stacks				
Roofing including roof space	2			
Rainwater fittings	1			
Main walls	1			
Windows, external doors and joinery	1			
External decorations	1			
Conservatories/porches	1			
Communal areas	-			
Garages and permanent outbuildings	1			
Outside areas and boundaries	1			
Ceilings	1			
Internal walls	1			
Floors including sub-floors	1			
Internal joinery and kitchen fittings	1			
Chimney breasts and fireplaces	1			
Internal decorations	1			
Cellars	-			
Electricity	1			
Gas	1			
Water, plumbing and bathroom fittings	1			
Heating and hot water	1			
Drainage	1			

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground	
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No	
3. Is there a lift to the main entrance door of the property?	Yes No X	
4. Are all door openings greater than 750mm?	Yes No X	
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No	
6. Is there a toilet on the same level as a bedroom?	Yes X No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X	
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No	

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The house has been substantially altered and extended, the attic has been converted to form two bedrooms and a bathroom, the garage has been extended and the ground floor layout has been altered to create the existing living room and kitchen/diner. Some double glazing and patio doors have been replaced. The porch has been extended.

The report assumes that all necessary Local Authority and other consents have been obtained for the alterations and the appropriate documentation including Building Warrants and Completion Certificates issued. If any works did not require consent then it has been assumed they meet the standards required by the Building Regulations or are exempt.

Photovoltaic panels have been mounted on the rear pitch of the roof, these are connected to the mains supply. Again they are assumed to comply with all relevant legislation.

Estimated reinstatement cost for insurance purposes

£245,000

Valuation and market comments

£230,000 (Two hundred and thirty thousand pounds).

There has been some revival in the residential market during the last three years with houses selling more readily.

Signed	Security Print Code [567686 = 0877] Electronically signed				
Report author	DAVID CRUICKSHANK				
Company name	DM Hall LLP				
Address	27 High Street, Elgin, IV30 1EE				
Date of report	5th September 2018				

Mortgage Valuation Report



Property Address						
Address8 LADY MARGARET DRIVE, LHANBRYDE, ELGIN, IV30 8PXSeller's NameMS CATRIONA SMITHDate of Inspection3rd September 2018						
Property Details						
Property Type	X House Bungalow Purpose built maisonette Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)					
Property Style	X Detached Semi detached Mid terrace End terrace Back to back High rise block Low rise block Other (specify in General Remarks)					
Does the surveyor be e.g. local authority, m	eve that the property was built for the public sector, Yes X No itary, police?					
Flats/Maisonettes onl						
Approximate Year of	No. of units in block					
Tenure						
X Absolute Ownership	Leasehold Ground rent £ Unexpired years					
Accommodation						
Number of Rooms	1 Living room(s) 4 Bedroom(s) 1 Kitchen(s) 2 Bathroom(s) WC(s) Other (Specify in General remarks)					
Gross Floor Area (exc	uding garages and outbuildings) 129 m ² (Internal) m ² (External)					
Residential Element (reater than 40%) X Yes No					
Garage / Parking /	utbuildings					
X Single garage Available on site?	Double garage Parking space No garage / garage space / parking space X Yes No					
Permanent outbuildin	s:					

Mortgage Valuation Report

Construction								
Walls	X Brick	Stone	Concrete	Timber frame	Othe	Other (specify in General Remarks)		
Roof	X Tile	Slate	Asphalt	Felt	Othe	r (specify in Gen	eral Remarks)	
Special Risks								
Has the property	suffered strue	ctural moveme	ent?			Yes	X No	
If Yes, is this rece	ent or progres	sive?				Yes	No	
Is there evidence, immediate vicinity	•	eason to antic	ipate subsidence	e, heave, landslip o	or flood in the	e Yes	X No	
If Yes to any of th	e above, pro	vide details in	General Remarl	(S.				
Service Connec	ctions							
Based on visual ir of the supply in G			ices appear to be	e non-mains, plea	se comment	on the type a	nd location	
Drainage	X Mains	Private	None	Water	X Mains	Private	None	
Electricity	X Mains	Private	None	Gas	X Mains	Private	None	
Central Heating	X Yes	Partial	None					
Brief description of	of Central He	ating:						
Gas radiator cen	tral heating.							
Site								
Apparent legal iss	uga ta ba ya	rified by the e	anvoyangar Dia	ana provide e brie	f description	in Conorol P	lomorka	
Rights of way	_	ives / access		ase provide a brie		red service conr		
Ill-defined boundar		_	tural land included w			er (specify in Ge		
Location								
Residential suburb		esidential within to	own / city 🗌 Mix	ed residential / comme	ercial 🗌 Mair	nly commercial		
X Commuter village	R	emote village	Isol	ated rural property	Othe	er (specify in Ge	neral Remarks)	
Planning Issues	S							
Has the property I	been extende	ed / converted	/ altered? X	Yes 🗌 No				
If Yes provide details in General Remarks.								
Roads								
Made up road	Unmade ro	ad Partly	completed new road	e Pedestrian a	access only	X Adopted	Unadopted	

Mortgage Valuation Report

General Remarks

The property is situated within an established and predominantly residential village, local amenities and facilities are available in close proximity.

The house has been maintained in a satisfactory state of repair for a property of its age, style and construction both internally and externally. Any items that require attention should be capable of remedy by routine maintenance work.

The house has been substantially altered and extended, the attic has been converted to form two bedrooms and a bathroom, the garage has been extended and the ground floor layout has been altered to create the existing living room and kitchen/diner. Some double glazing and patio doors have been replaced. The porch has been extended.

The report assumes that all necessary Local Authority and other consents have been obtained for the alterations and the appropriate documentation including Building Warrants and Completion Certificates issued. If any works did not require consent then it has been assumed they meet the standards required by the Building Regulations or are exempt.

Photovoltaic panels have been mounted on the rear pitch of the roof, these are connected to the mains supply. Again they are assumed to comply with all relevant legislation.

Essential Repairs

None.

Estimated cost of essential repairs £	Retention recommended? Yes	X No	Amount £	

Mortgage Valuation Report

Comment on Mortgageability

The property will form suitable security at the figure of value stated below.

Valuations	
Market value in present condition	£ 230,000
Market value on completion of essential repairs	£
Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 245,000
Is a reinspection necessary?	Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?	£ N/a
Is the property in an area where there is a steady demand for rented accommodation of this type?	Yes No

Security Print Code [567686 = 0877] Electronically signed by:-
DAVID CRUICKSHANK
MRICS
DM Hall LLP
27 High Street, Elgin, IV30 1EE
01343 548501
01343 540170
5th September 2018

PROPERTY QUESTIONNAIRE





Property Questionnaire

PROPERTY ADDRESS:	8 LADY MARGAROT DRIVE
	LHAN BRYDE MORAY
	1130 SPX

SELLER(S):		
	CATRION A SMITH	

COMPLETION DATE OF	
PROPERTY QUESTIONNAIRE:	7-9-18

PROPERTY QUESTIONNAIRE

NOTE FOR SELLERS

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the Date of Entry for the sale of your house, tell your solicitor or estate agent immediately.

1.	Length of ownership
	How long have you owned the property? 26 years
2.	Council Tax
	Which Council Tax band is your property in?
	A B C D E F G H
	Parking
	What are the arrangements for parking at your property?
	(Please indicate all that apply)
	Garage
	 Allocated parking space
	• Driveway
	Shared parking
	On street
	Resident permit
	Metered parking
	 Other (please specify):

	Conserv	ation Area	
	an area characte	property in a designated Conservation Area (i.e. of special architectural or historic interest, the or or appearance of which it is desirable to or enhance)?	Yes No Don't know
5.	Listed B	uildings	
	one (i.e.	property a Listed Building, or contained within a building recognised and approved as being of architectural or historical interest)?	Yes/No
6.	Alteratio	ns / additions / extensions	·
a.	out a	ng your time in the property, have you carried any structural alterations, additions or nsions (for example, provision of an extra /shower room, toilet, or bedroom)?	Yes/No
	12	<u>ve answered yes</u> , please describe the changes ou have made:	
	1998	Altic conversion malary 2 Bodrooms and bethroom	
	2007	Attached galage and Enlarged rearporch	
		rearporch	

	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	403
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent can arrange to obtain them.	
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property? <u>If you have answered yes</u> , please answer the three questions below:	Yes/No
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes/No
	(ii) Did this work involve any changes to the window or door openings?	Yes/No
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed): Diving from Window End god Diving from Herbary End godd Diving from Herbary End godd Diving from Herbary End godd	ten
	work to your solicitor or estate agent.	

7.	Central heating	
а.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom). If you have answered yes/partial – what kind of central heating is there?	Yes/No/ Partial
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air.)	
	GAS	
	If you have answered yes, please answer the 3 questions below:	
b.	When was your central heating system or partial central heating system installed?	
	1992	
C.	Do you have a maintenance contract for the central heating system?	Yes/No
	If you have answered yes, please give details of the company with which you have a maintenance agreement:	
	No contract but had annual checks.	
	Last check Angust 2018 by Neil Hadden Plumbes	
	Survisers	
d.	When was your maintenance agreement last renewed? (Please provide the month and year).	
d.	When was your maintenance agreement last renewed?	
d.	When was your maintenance agreement last renewed?	

8.	Energy Performance	Certificate		
	Does your propert Certificate which is le		Energy Performance ars old?	Yes/No
9.	Issues that may have	affected your	property	
a.	Has there been any s damage to your prop			Yes/No
	If you have answered any outstanding insu		mage the subject of	Yes/No
b.	Are you aware of the	existence of a	sbestos in vour	Yes/No
	property? If you have answered	<u>l yes</u> , please g	•	
10.	If you have answered	<u>l yes</u> , please g	•	
10. a.	If you have answered	vices are con	ive details:	
	If you have answered Services Please tick which ser	vices are con	ive details:	
	If you have answered Services Please tick which ser property and give det	vices are contails of the sup	ive details: nected to your oplier:	
	If you have answered If you have answered Services Please tick which ser property and give def Services Gas / liquid	vices are contails of the sup	ive details: nected to your oplier: Supplier	

	Mains drainage	yes			
	Telephone	Yes	BT		
	Cable TV / satellite	No			
	Broadband	482	ËĒ		
b.	Is there a septic tank	system at your	property	?	Yes/No
	If you have answered questions below:	<u>yes,</u> please an	swer the f	wo	
C.	Do you have approp from your septic tank		for the	discharge µ/A	Yes/No/ Don't Know
d.	Do you have a main tank?	itenance contra	act for yo	our septic	Yes/No
	If you have answere company with which	<u>d yes</u> , please you have a mai	give deta ntenance	ils of the contract:	
			NA		

11.	Responsibilities for Shared or Common Areas	
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details:	Yes/No/ Don't Know
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? <u>If you have answered yes</u> , please give details:	Yes/No/ Not applicable
C.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes
d.	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries? <u>If you have answered yes</u> , please give details:	Yes/No
е.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? <u>If you have answered yes</u> , please give details:	Yes/No

f.	As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.) <u>If you have answered yes</u> , please give details:	Yes/No
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property?	Yes/No
	If you have answered yes, please provide the name and address and give details of any deposit held and approximate charges:	
b.	Is there a common buildings insurance policy?	Yes/No/ Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes/No/ Don't know
C.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund.	

13.	Specialist Works	_
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes/No
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property	
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? <u>If you have answered yes</u> , please give details	Yes/No
C.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your	
	solicitor as soon as possible for checking. If you do not have them yourself <u>please write below who has</u> <u>these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	

	Guarantees are held by:						
14.	Guarantees						
a.	Are there any guarantees	or w	arrant	ies for any	/ of the		
(i)	following: Electrical work	No	Yes	Don't	 With title deeds	Lost	
(ii)	Roofing	No	Yes	Don't Know	With title deeds	Lost	
(iii)	Central heating	No	Yes	Don't know	With title deeds	Lost	
(iv)		No	Yes	Don't know	With title deeds	Lost	
(v) (vi)	Damp course Any other work or	No No	Yes Yes	Don't know Don't	With title deeds With title	Lost	
(••)	installations? (for example, cavity wall	NO		know	deeds		
	insulation, underpinning, indemnity policy)						
b,	If you have answered 'yes						
	of the work or installations to which the guarantee(s) relate(s):						
	2 2010 - Cavity				n-25yean	S	
	3) 2014 - Electrical contricate						
	@ 2014 - Photovol	b'd	in	L /low	Thomas .		

с. 15.	Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details: Boundaries So far as you are aware, has any boundary of your property been moved in the last 10 years? If you have answered yes, please give details:	Yes/No Yes/No/ Don't Know
16.	Notices that affect your property	
	In the past 3 years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	Yes/No/ Don't know
b.	that affects your property in some other way?	Yes/No/ Don't
c.	that requires you to do any maintenance, repairs or improvements to your property?	know Yes/No/ Don't know

If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.

Declaration by the seller(s)/or other authorised body or person(s):

I / We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :

Date: 2-9-18.

DM Hall Offices

Aberdeen 01224 594172

Cumbernauld

01236 618900

01334 844826

01387 254318

01382 873100

Ayr

Cupar

Dumfries

Dundee

Galashiels 01896 752009

Glasgow (North) 01292 286974 0141 332 8615

> Glasgow (South) 0141 636 4141

> > Hamilton 01698 284939

Inverness 01463 241077

Inverurie 01467 624393

Irvine 01294 311070

Kirkcaldy 01592 598200 Livingston 01506 490404

Musselburgh 0131 665 6782

Oban 01631 564225

Paisley 0141 887 7700

Perth 01738 562100

Peterhead 01779 470220

Stirling 01786 475785



Dunfermline 01383 621262

Edinburgh 0131 477 6000

Elgin 01343 548501

Falkirk 01324 628321