







- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



survey report on:

	12 St Johns Court, Hay Street, Elgin, IV30 1NG
--	---------------------------------------------------------

	Customer	Mr CA Toynton
--	----------	---------------

Customer address 16 Kyd Drive, Elgin, IV 30 4GN	
---------------------------------------------------------------------	--

Prepared by Harvey Donaldson And Gibson

Date of inspection 25th July 2018	
---------------------------------------	--



HARVEY DONALDSON & GIBSON CHARTERED SURVEYORS

12 St Johns Court, Hay Street, Elgin, IV30 1NG 25th July 2018 Roz Melen

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The ultimate holding company of Harvey Donaldson & Gibson is Countrywide plc. In Scotland, Countrywide plc also own Slater Hogg & Howison and Countrywide North. A full list of estate agents owned or under franchise to Countrywide plc is available on request. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Х

Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information

contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

Terms and Conditions

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be

researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The property is a third floor, purpose built, one bedroom flat set in communal garden grounds.	
Accommodation The accommodation comprises the following:		
	Hallway, living room, kitchen, bedroom, bathroom.	

Gross internal floor area (m²)	The gross internal floor area extends to 64 square metres or thereby.

Neighbourhood and location	The property is located in an established residential area on the edge of Elgin town centre.
	A full range of amenities are available within the town.
	The property is adjacent to a university and close to a hospital and a primary school.

Age	Approximately 83 years

Weather	Dry

Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	The chimney is located on the flat roof and is one of four similar chimney stacks; it is of a rendered masonry construction with three clay pots and lead flashings.

Roofing including roof space	The roof is flat and covered in mineral roofing felt.
	Access to the external flat roof area is via a roof light/hatch at the top of the common stair.

Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Rainwater fittings are metal and it is assumed they were originally fitted at the time of construction.

Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of an ashlar and rendered stone construction.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	Windows are double glazed PVC replacement units.
	The entry door is timber and is assumed to have been originally fitted at the time of construction.

External decorations	Visually inspected.
	External decorations comprise painted masonry and metal rain water fittings.

Conservatories / porches	N/A

Communal areas	Circulation areas visually inspected.
	There are communal gardens to the front and rear; the latter adjoins some privately owned gardens.
	Outside communal areas are suitably bounded by shrubbery, walls and a gate.
	The flatted building is approached via a shared walkway, which extends to the rear.
	The building is accessed via a shared timber double door to the front; this has a security access panel. This in turn leads to an inner double door.
	The rear of the building is accessed via a shared timber door.
	There is a shared storage area at the bottom of the stair.
	The common stairs are concrete.
	Windows to the common stair are metal framed and single glazed units.

Garages and permanent outbuildings N/A

Outside areas and boundaries	Visually inspected.
	There is an allocated parking space to the front, within a shared parking area.
	Each parking space has a locking post to prevent unauthorised parking.

Ceilings	Visually inspected from floor level.
	Ceilings appear to be lath & plaster.

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls appear to be of a timber frame construction and finished in lath & plaster.

Floors including sub floors	Floors are suspended timber.
5	

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Internal doors are timber.
	Door surrounds and skirting boards are timber.
	Kitchen fittings consist of floor and wall mounted units.

Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	The chimney breast in the living room is plastered masonry; the fireplace has been boarded over.

Internal decorations	Visually inspected.
	Internal walls and ceilings are painted and/or papered.
	Internal joinery is painted and/or stained or varnished.

Cellars	N/A

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains electricity is installed.
	The consumer unit/fuse box and meter are located in a hall cupboard.
	The switch and socket outlets are plastic and the wiring is sheathed with PVC, where visible.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	The property is connected to mains gas.
	The meter is located beneath the gas-fired boiler in the kitchen.


Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	There is a mains water supply.
	Pipework is a mixture of copper and PVC manufacture where visible.
	The bathroom has a bath with shower over, a basin and a w.c.

Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Heating and hot water is provided by a gas-fired combi boiler located in the kitchen.
	The boiler flue exits the flat at the rear elevation.
	Heating to rooms is provided by water filled radiators.

Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	The property is connected to the public drainage system.

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property has hard-wired smoke and heat detectors and a carbon monoxide detector.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.
	Many materials used for construction and decoration prior to 1999 contained asbestos, and these may be hidden from view at the time of inspection. Appropriate precautions should be taken if any sanding, redecoration or removal is planned; should removal be contemplated, this should only be carried out by a licensed asbestos removal contractor.
	The property was inspected within the limits imposed by occupation which included, throughout, closely nailed and fixed fitted carpeting, floor coverings, furniture, etc.
	This report does not constitute a full and detailed description of the property and a structural investigation was not carried out.
	No inspection was undertaken of woodwork or other parts of the structure which are covered, unexposed or otherwise inaccessible and as a result no guarantee can be given that such parts of the structure are free from rot, beetle or other defects.
	No removal of internal linings has been carried out in order to ascertain the condition of hidden parts and no warranty can be given regarding the areas not specifically referred to in this report.
	The external building fabric has been inspected from ground level only within the boundaries and where possible from adjoining public property.



2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement		
Repair category	1	
Notes	There is evidence of previous movement in the form of localised hairline cracking to the external building fabric. The movement is considered to be longstanding in nature with no indication of recent structural deterioration. On the basis of a limited single inspection, no further significant movement is anticipated.	

Dampness, rot and infestation	
Repair category	2
Notes	Evidence of localised penetrating dampness was noted to a small area at the rear/gable corner bedroom wall.

Chimney stacks	
Repair category	1
Notes	No obvious significant defects were noted to chimneyheads, allowing for normal weathering.

Roofing including roof space	
Repair category	1
Notes	The main roof appears satisfactory.
	The limited life expectancy of flat roofs should be fully appreciated.

Rainwater fittings	
Repair category	2
Notes	Some metal rainwater fittings show signs of localised, minor rust corrosion.

Main walls	
Repair category	1
Notes	The main walls are in reasonable condition allowing for age and weathering.

Windows, external doors and joinery	
Repair category	1
Notes	Windows, external doors and joinery appear satisfactory.

External decorations	
Repair category	2
Notes	Some external decoration to metal rainwater fittings has weathered.

Conservatories/porches	
Repair category	-
Notes	N/A

Communal areas	
Repair category	2
Notes	Some boundary walls are cracked.
	Wear and tear is apparent to decorations within the common close.

Garages and permanent outbuildings	
Repair category	-
Notes	N/A

Outside areas and boundaries	
Repair category	-
Notes	The allocated parking area appears satisfactory.

Ceilings	
Repair category	1
Notes	There are areas of unevenness and minor blemishes to ceiling surfaces. Areas of minor staining were noted to the bathroom ceiling. When tested with an electronic moisture meter, affected areas were dry.

Internal walls	
Repair category	1
Notes	The plaster finishes appear generally sound with only minor evidence of unevenness and impact damage.

Floors including sub-floors	
Repair category	1
Notes	Floors are satisfactory within the limitations of the inspection.

Internal joinery and kitchen fittings	
Repair category	1
Notes	Internal joinery and kitchen fittings are satisfactory.
	Internal doors have glazed panels which may not be of an approved safety type.

Chimney breasts and fireplaces	
Repair category	1
Notes	The chimney breast and fireplace appear satisfactory.
	No inspection of inner flue linings was possible.
	All blocked chimneys/fireplaces should be vented in order to avoid a build up of condensation dampness.

Internal decorations		
Repair category	1	
Notes	Internal decorations are satisfactory. Many materials used prior to 1999 contained asbestos. Appropriate precautions should be taken if any sanding or redecoration is planned, and should removal be contemplated, this should only be carried out by a licensed asbestos removal contractor.	

Cellars	
Repair category	-
Notes	N/A

Electricity	
Repair category	2
Notes	It is likely that only properties recently rewired will have electrical installations that fully comply with current regulations introduced in 2015.
	The electrical system is relativity modern but has an older style fuse box; however, there evidence of a recent test.
	It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check.

Gas	
Repair category	1
Notes	No obvious significant defects were noted. It is recommended best practice that all gas installations should be checked periodically. This should be regarded as a routine safety and maintenance check.

F Water, plumbing and bathroom fittings	
Repair category	1
Notes	Water, plumbing and bathroom fittings appear satisfactory. The plumbing in the majority of properties built before 1945 was carried in lead. Given the age of the property, there is a risk that there could be lead piping in concealed locations. Should this be encountered, it would be essential to have this replaced, on health grounds.

Heating and hot water	
Repair category	1
Notes	The gas-fired system was operational at the time of inspection and appeared serviceable.

Drainage	
Repair category	1
Notes	No obvious significant defects were noted to the drainage system, within the limitations of the inspection.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	2
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	2
Main walls	1
Windows, external doors and joinery	1
External decorations	2
Conservatories/porches	-
Communal areas	2
Garages and permanent outbuildings	-
Outside areas and boundaries	-
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	2
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Third Floor
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes X No
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The tenure is understood to be Outright Ownership.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

There is an allocated parking space to the front, within a shared parking area. The legal advisor should confirm Title.

Reference to the Titles will ascertain the exact ownership, maintenance and liability of common areas and factoring charges. We are informed by the owner that a monthly 15 pounds factoring charge applies.

Estimated reinstatement cost for insurance purposes

We are of the opinion that the current reinstatement value for insurance purposes can be fairly stated in the region of:

£150,000 (one hundred and fifty thousand pounds)

Valuation and market comments

In its present condition the opinion of valuation for the Outright Ownership interest of the property with vacant possession on 25th July 2018 is:

£95,000 (ninety five thousand pounds)

This valuation is based on actual sales of three comparable properties within the last six months.

Signed	Security Print Code [460443 = 5074]O Electronically signed
	,,,

Report author	Mark McClelland-Jones

Company name	Harvey Donaldson And Gibson

Address	Park House, South Street, Elgin, Moray, IV30 1JB
---------	--------------------------------------------------

	25th July 2018
12 St Johns Court, Hay Street,	



Property Address	
Address Seller's Name Date of Inspection	12 St Johns Court, Hay Street, Elgin, IV30 1NG Mr CA Toynton 25th July 2018
Property Details	
Property Type	House Bungalow Purpose built maisonette Converted maisonette X Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)
Property Style	Detached Semi detached Mid terrace End terrace Back to back High rise block X Low rise block Other (specify in General Remarks)
Does the surveyor be e.g. local authority, m	ieve that the property was built for the public sector,
Flats/Maisonettes onl Approximate Year of	No. of units in block 12
Tenure	
X Absolute Ownership	Leasehold Ground rent £ Unexpired years
Accommodation	
Number of Rooms	1 Living room(s) 1 Bedroom(s) 1 Kitchen(s) 1 Bathroom(s) 1 WC(s) 0 Other (Specify in General remarks)
	Iuding garages and outbuildings) m² (Internal) 64 m² (External) greater than 40%) X Yes No
Garage / Parking /	Dutbuildings
Single garage Available on site?	Double garage X Parking space No garage / garage space / parking space X Yes No
Permanent outbuildin	JS:
INUTIE	

Construction							
Walls	Brick	X Stone	Concrete	Timber fram	ne Othe	er (specify in Gen	eral Remarks)
Roof	Tile	Slate	Asphalt	X Felt	Othe	er (specify in Gen	eral Remarks)
Special Risks							
Has the property s	suffered struct	ural moveme	ent?			X Yes	No
If Yes, is this rece	nt or progress	ive?				Yes	X No
Is there evidence, immediate vicinity		ison to antici	pate subsidence	e, heave, landsli	ip or flood in the	e Yes	X No
If Yes to any of the	e above, provi	de details in	General Remar	KS.			
Service Connec	tion						
Based on visual ir of the supply in Ge			ces appear to be	non-mains, ple	ease comment o	on the type ar	nd location
Drainage	X Mains	Private	None	Wate	r X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description o	of Central Heat	ing:					
Site							
Apparent legal iss	ues to be veri	fied by the co	onveyancer. Ple	ase provide a bi	rief description	in General Re	emarks.
Rights of way	Shared drive	es / access	Garage or othe	amenities on sepa	rate site	red service conn	ections
Ill-defined boundar	ies	Agricult	ural land included w	ith property	Oth	er (specify in Gei	neral Remarks)
Location							
Residential suburb	X Res	idential within to	wn / city 🗌 Mix	ed residential / com	mercial 🗌 Mai	nly commercial	
Commuter village	Ren	note village	Isol	ated rural property	Oth	er (specify in Gei	neral Remarks)
Planning Issues	\$						
Has the property b If Yes provide deta			/ altered?	Yes X No			
Roads							
X Made up road	Unmade road	Partly	completed new road	d Pedestria	an access only	Adopted	Unadopted

General Remarks

When inspected within limits imposed by occupation, the general condition of the property appears consistent with its age and type of construction, and no obvious significant defects were noted which would adversely affect the subjects as a mortgage security.

Essential Repairs

Estimated cost of essential repairs £ [

Retention recommended? Yes X No

X No Amount £

Comment on Mortgageability

The property affords adequate security for loan purposes based on the valuation figure, subject to indiv	ridual
lender's criteria.	

Valuations	
Market value in present condition	£ 95,000
Market value on completion of essential repairs	£
Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 150,000
Is a reinspection necessary?	Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?	£
Is the property in an area where there is a steady demand for rented accommodation of this type?	Yes No
Declaration	

Signed	Security Print Code [460443 = 5074]O Electronically signed by:-
Surveyor's name	Mark McClelland-Jones
Professional qualifications	AssocRICS
Company name	Harvey Donaldson And Gibson
Address	Park House, South Street, Elgin, Moray, IV30 1JB
Telephone	07725 428687
Fax	01343 542853
Report date	25th July 2018

Energy Performance Certificate (EPC)

Scotland

Dwellings

12 ST JOHNS COURT, HAY STREET, ELGIN, IV30 1NG

Dwelling type:	Top-floor flat
Date of assessment:	25 July 2018
Date of certificate:	25 July 2018
Total floor area:	64 m ²
Primary Energy Indicator:	443 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel: 0180-2455-1030-9028-7021 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

You can use this document to:

B

Not environmentally friendly - higher CO₂ emissions

D

F

G

(81-91)

(69-80)

(55-68)

(39-54


(21-38)

(1-20)

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£3,159	See your recommendations	
Over 3 years you could save*	£1,668	report for more information	

^{*} based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band E (51)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band E (45)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

76

45

Recommended measures	Indicative cost	Typical savings over 3 years	Available with Green Deal
1 Flat roof or sloping ceiling insulation	£850 - £1,500	£885.00	\bigcirc
2 Internal or external wall insulation	£4,000 - £14,000	£447.00	\bigcirc
3 Floor insulation (suspended floor)	£800 - £1,200	£225.00	\bigcirc

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.



The Green Deal may allow you to make your home warmer and cheaper to run at no up-front capital cost. See your recommendations report for more details. THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

12 ST JOHNS COURT, HAY STREET, ELGIN, IV30 1NG 25 July 2018 RRN: 0180-2455-1030-9028-7021

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls Granite or whinstone, as built, no insulation (assumed)		*****	\star \bigstar \bigstar \bigstar \bigstar
Roof	Flat, no insulation (assumed)	****	$\bigstar \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit \clubsuit $
Floor	Suspended, no insulation (assumed)	—	—
Windows	Fully double glazed	★★★☆	★★★☆
Main heating	Boiler and radiators, mains gas	★★★☆	★★★ ☆
Main heating controls	Programmer, TRVs and bypass	★★★☆☆	★★★☆☆
Secondary heating	None	—	
Hot water	From main system	★★★☆	★★★★☆
Lighting	Low energy lighting in 14% of fixed outlets	★★☆☆☆	★★☆☆☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 78 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 5.0 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.9 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

12 ST JOHNS COURT, HAY STREET, ELGIN, IV30 1NG 25 July 2018 RRN: 0180-2455-1030-9028-7021

Estimated energy costs for this home				
	Current energy costs	Potential energy costs	Potential future savings	
Heating	£2,601 over 3 years	£1,059 over 3 years		
Hot water	£282 over 3 years	£285 over 3 years	You could	
Lighting	£276 over 3 years	£147 over 3 years	save £1,668	
Totals	£3,159	£1,491	over 3 years	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement		Green
		indicative cost	holcative cost per year		Environment	Deal
1	Flat roof or sloping ceiling insulation	£850 - £1,500	£295	D 64	D 61	
2	Internal or external wall insulation	£4,000 - £14,000	£149	C 70	C 70	
3	Floor insulation (suspended floor)	£800 - £1,200	£75	C 74	C 75	
4	Low energy lighting for all fixed outlets	£30	£36	C 75	C 76	

Measures which have a green deal tick of are likely to be eligible for Green Deal finance plans based on indicative costs. Subsidy also may be available for some measures, such as solid wall insulation. Additional support may also be available for certain households in receipt of means tested benefits. Measures which have an orange tick of may need additional finance. To find out how you could use Green Deal finance to improve your property, visit www.greenerscotland.org or contact the Home Energy Scotland hotline on 0808 808 2282.

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Flat roof or sloping ceiling insulation

Insulating a flat roof or sloping ceiling will significantly reduce heat loss through the roof; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulation can be placed on top of the roof under the waterproof membrane and should particularly be considered when the waterproofing needs to be replaced. Further information about roof insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check with your local authority building standards department.

2 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide longlasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

3 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

4 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

You could receive Renewable Heat Incentive (RHI) payments and help reduce carbon emissions by replacing your existing heating system with one that generates renewable heat and, where appropriate, having your loft insulated and cavity walls filled. The estimated energy required for space and water heating will form the basis of the payments. For more information go to www.energysavingtrust.org.uk/scotland/rhi.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	14,981	N/A	N/A	(2,607)
Water heating (kWh per year)	1,919			

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. Mark McClelland-Jones
Assessor membership number:	EES/020000
Company name/trading name:	Harvey Donaldson & Gibson Chartered Surveyors
Address	The Park House Business Centre
	South Street
	Elgin
	IV30 1JB
Phone number:	01343547844
Email address:	frances.wilson@hdg.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Opportunity to benefit from a Green Deal on this property

Under a Green Deal, the cost of the improvements is repaid over time via a credit agreement. Repayments are made through a charge added to the electricity bill for the property.

To see which improvements are recommended for this property, please turn to page 3. You can choose which improvements you want to install and ask for a quote from an authorised Green Deal provider. They will organise installation by an authorised Green Deal installer. If you move home, the responsibility for paying the Green Deal charge under the credit agreement passes to the new electricity bill payer.

For householders in receipt of income-related benefits, additional help may be available.

To find out more, visit www.greenerscotland.org or call 0808 808 2282.





PROPERINY QUESTIONINAIRE


Property address	12, St. John's Court Hay street
	Hay street
	Eigin IV30 LNG
	IV30 ING

 Seller(s)	MR C.A. TOYNTON	

Completion date of property	29/7/18
questionnaire	



ENERGY REPORT PROPERTY QUESTIONNAIRE VALUATION REPORT



....Dool Air

6

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please
 answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership		
	How long have you owned the property? 54rs		
2.	Council tax		
	Which Council Tax band is your property in? (Please tick)		
	$A \square B \square C \square D \square E \square F \square G \square H \square$		
3.	Parking		
	What are the arrangements for parking at your property?		
	(Please tick all that apply)		
	Garage		
	Allocated parking space		
	Driveway		
	Shared parking		
	On street		
	Resident permit		
			h
	 Metered parking Other (please specify): "Reserved" & lock of the specify of the second sec	ble of - rue	
	• Other (please specify): "Reserved & Tock of particular part		
4.	Concentration area		
	that is a designated Conservation Area (that is an area	Yes	
	a selectorization of historical interest, the origination	No	YA
	appearance of which it is desirable to preserve or enhance)?	Don't know	
5.	Listed buildings		
	the support of the steel Building, or contained within one	Nee	
	(that is a building recognised and approved as being of	Yes No	H
	special architectural or historical interest)?	NO	
6.	Alterations/additions/extensions		
a.	(i) During your time in the property, have you carried out any	Vee	П
	structural alterations, additions or extensions (for example,	Yes No	H
	provision of an extra bath/shower room, toilet, or bedroom)?		VEL.

	103	1		1	
	ir	7	2		
	14	J	7		
1	1	7			
e d	7				

PROPERTY QUESTIONINAIRE

IVIALD

	 - Second and Additional Statistics - Second and Additional Statistics 	
	If you have answered yes, please describe below the changes which you have made:	
	 (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them: 	Yes No
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below:	Yes D No
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes No
	(ii) Did this work involve any changes to the window or door openings?	Yes D No
	(iii) Please describe the changes made to the windows doors, or approximate dates when the work was completed): Please give any guarantees which you received for this work to	
	estate agent.	
7. a.	Central heating Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).	Yes No Partial
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	Gas - fired
	If you have answered yes, please answer the three questions below:	
	i) When was your central heating system or partial central heating system installed?	2003

PROPERTY QUESTIONNAIRE

	(ii) Do you have a maintenance contract for the central heating system?	Yes No	B
	If you have answered yes, please give details of the company with which you have a maintenance contract:	STAYWARI Service the annually	M, Elgin boiler
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	NA	
8.	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes No	
9.	Issues that may have affected your property		
а.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes No	
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes No	
b.	Are you aware of the existence of asbestos in your property?	Yes	
	If you have answered yes, please give details:	No	

E



PROPERTY QUESTIONINAIRE

010000			
	(ii) Do you have a maint		
	(ii) Do you have a maintenance contract for the central heating system?	Yes No	A
	If you have answered yes, please give details of the company with which you have a maintenance contract:	STAYWAR service the annually	y, Elgin boiler 2 (
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	NA	
8.	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes No	F
9.	Issues that may have affected your property		
а.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes No	J
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes No	
b.	Are you aware of the existence of asbestos in your property? If you have answered yes, please give details:	Yes	

	1	1
		1
	7	
5		

PROPERTY QUESTIONNAIRE

10. Services				
a. Please tick which services ar supplier:	e connected to your pro	operty and give	e details of the	
Services	Connected	Supplier		
Gas or liquid petroleum gas		NPO	Wer H WATE	
Water mains or private water supply				<
Electricity		NPO	wer	
Mains drainage	\checkmark	Scoths	H WATER	
Telephone	NA		1A	
Cable TV or satellite	NIA		[A	
Broadband	NA	N	IA	
b. Is there a septic tank system If you have answered yes below: (i) Do you have appropriation your septic tank? (ii) Do you have a mainter If you have answered yes with which you have a mainter	te consents for the disc nance contract for your please give details of t	harge from septic tank?	Yes No Don't know Yes No	
11. Responsibilities for share	d or common areas			
a. Are you aware of any responsion anything used jointly, such private road, boundary, or	onsibility to contribute to as the repair of a share garden area?	a unit of	Yes No Don't know	
 If you have answered yes, ↓ 15 p/m communative pairs, gardens b. Is there a responsibility to of the roof, common stairw 		ee to corev mmunal maintenance as?	Don't know	ACC -
If you have answered yes, p Paid by the COMM	unal Mainten	ance Ree -	-£15p/m p Ves	er Alat
c. Has there been any major r the roof during the time you	epair or replacement of a	any part of	Yes No	J.

				1 1 1 1 1 M 1	
		18. J	and the second	Charles Statistics	and the second
$(1,1) \in \mathbb{R}^{n}$					• =
1. J.	1.0	t San Sin		RO	1
			- Perfect	The sector sector of	ALC: NO
			1 N N N		

5

PROPERTY QUESTIONNAIRE

?

d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to	Yes D No D	
	maintain your boundaries? If you have answered yes, please give details:		
	the state of the s	Yes	
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	No Va	
	If you have answered yes, please give details:	Yes	
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	No	
	If you have answered yes, please give details:		
12.	Charges associated with your property	Yes	
a.	factor or property manager for your party	No Ur	
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	but Managed by residents'	
	charges.	association Yes	
b.	Is there a common buildings insurance policy?	No Don't know	
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	ular basis for the	
C.	Please give details of any other charges you have to pay on a regulater of common areas or repair works, for example to a resider maintenance or stair fund. See question IIB - £15p/N communal Nair		r flat
			4
13.	Specialist works As far as you are aware, has treatment of dry rot, wet rot, damp	Yes I	-
а.	or any other specialist work ever been been been been been been been be		
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.		
	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	Yes D No	-
b.			1

PROPERTY QUESTIONNAIRE

	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	Yes No	
C.	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself, your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:		

14.	Guarantees					
a.	Are there any guarantees or warranties for	or any of	the follow	wing:	Landal atal-	
		No	Yes	Don't know	With title deeds	Lost
(i)	Electrical work		N			
(ii)	Roofing					
(iii)	Central heating					
(iv)	National House Building Council (NHBC)	Į.				
(v)	Damp course	J.				
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	₽ ₽				
b.	If you have answered 'yes' or 'with title of installations to which the guarantee(s) re	- Cafot	y Row	rd re-	to to com	ply
C.	Are there any outstanding claims under a listed above?	any of the	e guarant	ees	Yes No	
	<u>If you have answered yes</u> , please give de	etails:				
15.	Boundaries					
	So far as you are aware, has any bounda been moved in the last 10 years? If you have answered yes, please give de		r propert	У	Yes No Don't know	
16.	Notices that affect your property					
	In the past three years have you ever re	eceived a	notice:			
а.	advising that the owner of a neighbour a planning application?	ing prop	erty has	made	Yes No	

	PROPERTY QUES	TIONNA
Ľ	Y.	oranda e a successive en en en estador e de la construcción de la construcción de la construcción de la constru La construcción de la construcción d
b.	that affects your property in some other way?	Yes No
с.	that requires you to do any maintenance, repairs or improvements to your property?	Yes No

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :

C.A. Togaton

Date: 29/7/18





The Park House Business Centre, South Street, Elgin IV30 1JB 01343 547844 elgin.residential@hdg.co.uk