

HARVEY DONALDSON & GIBSON

CHARTERED SURVEYORS

Parent to HomeReportScotland.scot







- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



survey report on:

,	
Property address	28 Riddock Gardens, Forres, IV36 2QE
Customer	Mr R Stevenson
Customer address	
Prepared by	Harvey, Donaldson and Gibson
Date of inspection	16th August 2023



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The ultimate holding company of Harvey Donaldson & Gibson is Countrywide plc. In Scotland, Countrywide plc also own Slater Hogg & Howison and Countrywide North. A full list of estate agents owned or under franchise to Countrywide plc is available on request. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
 or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information

contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property:
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be

researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	First floor flat in purpose built two and three storey block of five flats with the flats sharing communal access.
Accommodation	First floor – hall, living room and kitchen on open plan, master bedroom with en suite shower room and WC, further bedroom and main bathroom with WC.
Gross internal floor area (m²)	65
Neighbourhood and location	The property is situated in a modern residential development in the town of Forres. Surrounding properties are of similar age and character. Usual amenities and transport links are available within a reasonable distance.
Age	7 years.
Weather	Dry.
	•
Chimney stacks	None.

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof is pitched and tiled.
	Our inspection of the rear roof pitch was restricted due to the position of the building on site.
	No inspection of the roof space was possible as this is presumably obtained via the upper flat. No comment can therefore be made of the condition of roof timbers.
Dainwaten fittin na	
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Rainwater fittings are of uPVC.
	gg
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	Main walls are of conventional timber framed construction with block outer leaf, externally mainly rendered although with part timber cladding. The overall wall thickness is approximately 400mm.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	Windows are of triple glazed uPVC framed types, with the flat
	entrance door of timber composite construction. Eaves are lined in uPVC. There is part timber wall cladding.
External decorations	Visually inspected.
Conservatories / porches	None.

Communal areas	Circulation areas visually inspected.
	There is communal entrance and stair. A security entry system is installed (not tested).
Garages and permanent outbuildings	None.
Outside areas and boundaries	Visually in an asked
Outside areas and boundaries	Visually inspected. There is surrounding communal garden area partly defined by timber fencing. Garden areas are mainly laid to grass. There is block paved communal parking.
Ceilings	Visually inspected from floor level.
	Ceilings are plasterboard lined.
Internal walls	
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Internally all walls are plasterboard lined.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Flooring is of suspended timber construction. Our inspection of flooring was restricted due to close fitted floor coverings throughout.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were
	moved.
	Kitchen units were visually inspected excluding appliances.
	Internal joinery includes moulded faced composite doors. The kitchen is equipped with a typical range of serviceable units.
Chimney breasts and fireplaces	None.
Internal decorations	Visually inspected.
1	

Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Electricity is from mains supply with meter and consumer unit located in hall cupboard. The visible installation is 13 amp power outlets.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Gas is from mains supply with meter housing located externally.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Water is from mains supply with stop valve apparently located in hall cupboard. The bathroom is fitted with three piece suite with shower over the bath. The en suite shower room is fitted with three piece suite.
Heating and hot water	Accessible parts of the system were visually inspected apart
Trouting and not water	from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Gas fired central heating supplies radiators via a 'Potterton' boiler located in the kitchen.
	Hot water is provided by the central heating system on instant demand, with no separate storage tank.
Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	Drainage is connected to the public sewer.

Fire, smoke and burglar alarms

Visually inspected.

No tests whatsoever were carried out to the system or appliances.

Smoke detectors are fitted.

Scottish government regulations came into effect in February 2022 which require each property to have linked smoke and heat detectors and if gas / carbon burning appliances are present then a carbon monoxide alarm fitted. Purchasers should satisfy themselves with regards to compliance.

Any additional limits to inspection

For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.


The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

Floors were covered at the time of inspection. No close inspection was possible to enclosed areas beneath and around washing appliances and sanitary fittings.

It will be appreciated that parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.

It was dry on the date of inspection. Leakage and water penetration within roof spaces, around window openings etc are sometimes only visible during or immediately after, adverse weather conditions.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- 5 Ridge ventilation
- 6 Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10) Dormer flashing
- 11) Dormer cheeks
- 12) Sarking
- (13) Roof felt
- (14) Trusses
- (15) Collar
- 16 Insulation
- 17) Parapet gutter
- 18) Eaves guttering
- (19) Rainwater downpipe
- 20) Verge boards/skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- 25) Window pointing
- 6) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- 31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33 Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- Floor joists
- 38) Floorboards
- 39) Water tank
- 40 Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	We found no evidence of significant structural movement. There will be a tendency for natural thermal / moisture movement to occur, usually indicated by cracking adjacent to openings.

Dampness, rot and infestation	
Repair category	1
Notes	No evidence of dampness, rot or infestation was noted to exposed internal areas.

Chimney stacks	
Repair category	-
Notes	Not applicable.

Roofing including roof space	
Repair category	1
Notes	No significant matters.

Rainwater fittings	
Repair category	1
Notes	No significant matters.

Main walls	
Repair category	1
Notes	No significant matters. As the building within which the subject property is located does not, based on our visual inspection, give rise to any specific cause for concern and / or the RICS External Wall System Review Process is not considered to be applicable, based on current RICS guidance, we have assumed that it is free from any / all fire safety defects and is fully compliant with and meets all current building regulation and fire safety standards. However, this decision is not a guarantee that works will not be required in future.

Windows, external doors and joinery	
Repair category	1
Notes	Some windows stick slightly in operation.

External decorations	
Repair category	1
Notes	No significant matters.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	1
Notes	No significant matters.

Garages and permanent outbuildings	
Repair category	-
Notes	Not applicable.

Outside areas and boundaries	
Repair category	1
Notes	No significant matters.

Ceilings	
Repair category	1
Notes	There is typical isolated cracking due to natural thermal / moisture movement.

Internal walls	
Repair category	1
Notes	No significant matters.

Floors including sub-floors	
Repair category	1
Notes	No significant matters.
	Spillage often occurs to enclosed areas around sanitary fittings and washing appliances with consequent risk of deterioration or decay. The need for repairs can be revealed when coverings and fittings are removed.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No significant matters.

Chimney breasts and fireplaces	
Repair category	-
Notes	Not applicable.

Internal decorations	
Repair category	1
Notes	No significant matters.

Cellars	
Repair category	-
Notes	Not applicable.

Electricity	
Repair category	1
Notes	The electrical installation is tested through until December 2023. It is recommended good practice that electrical systems should be inspected periodically by qualified electrician, approximately every five years and on a change of occupancy. This should be regarded as a routine safety and maintenance check. Only the most recently constructed or re-wired properties will have installations which fully comply with present IET regulations.

Gas	
Repair category	1
Notes	A Gas Safe registered engineer can give further advice on the gas supply. In the interests of safety it is prudent practice to have annual tests carried out.

Water, plumbing and bathroom fittings			
Repair category	1		
Notes	The kitchen tap was dripping consistently at the time of inspection. It is important to maintain a watertight seal around the various fittings to prevent water spillage causing damage to surrounding surfaces and concealed areas.		

Heating and hot water				
Repair category	1			
Notes	It is assumed that the gas boiler and central heating system have been serviced and maintained to date. The advice of a Gas Safe registered heating engineer will be required prior to use.			

Drainage	
Repair category	1
Notes	No significant matters.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	-
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	1
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	-
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	First floor		
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X		
3. Is there a lift to the main entrance door of the property?	Yes No X		
4. Are all door openings greater than 750mm?	Yes No X		
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No		
6. Is there a toilet on the same level as a bedroom?	Yes X No		
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No		
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No		

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The tenure is assumed to be Outright Ownership.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

As the building within which the subject property is located does not, based on our visual inspection, give rise to any specific cause for concern and / or the RICS External Wall System Review Process is not considered to be applicable, based on current RICS guidance, we have assumed that it is free from any / all fire safety defects and is fully compliant with and meets all current building regulation and fire safety standards. However, this decision is not a guarantee that works will not be required in future. It is an essential condition of the valuation reported that confirmation be sought from your chosen Lender of their acceptance of current RICS guidance.

The valuation assumes there is a suitable and enforceable shared maintenance / management agreement for the block and surroundings.

It is assumed that there are local authority consents and certifications along with Premier insurance documentation from Springfield Properties and it is assumed that this documentation will be made available.

Estimated reinstatement cost for insurance purposes

£230,000 (Two hundred and thirty thousand pounds).

This figure is the estimate of the cost of rebuilding the premises and bears no relationship to market value.

Valuation and market comments

In its present condition the opinion of valuation for the Outright Ownership interest with vacant possession on 16th August 2023 is £130,000 (One hundred and thirty thousand pounds).

Signed	Security Print Code [585236 = 6881]O Electronically signed					
Report author	John I Dougan					
Company name	Harvey, Donaldson and Gibson					

Address	Duncan House, Wester Inshes Place, Inverness, Highland, IV2 5HZ				
Date of report	17th August 2023				



Property Address							
Address Seller's Name Date of Inspection	28 Riddock Gardens, Forres, IV36 2QE Mr R Stevenson 16th August 2023						
Property Details							
Property Type	House Bungalow Purpose built maisonette Converted maisonette X Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)						
Property Style	□ Detached □ Semi detached □ Mid terrace □ End terrace □ Back to back □ High rise block ▼ Low rise block □ Other (specify in General Remark						
Does the surveyor be e.g. local authority, m	ieve that the property was built for the public sector, Yes X No litary, police?						
Flats/Maisonettes only							
Approximate Year of 0							
Tenure							
X Absolute Ownership	Leasehold Ground rent £ Unexpired years						
Accommodation							
Number of Rooms	1 Living room(s) 2 Bedroom(s) 1 Kitchen(s) 2 Bathroom(s) 0 WC(s) 0 Other (Specify in General remarks)						
Gross Floor Area (exc	luding garages and outbuildings) 65 m² (Internal) 75 m² (External)						
Residential Element (greater than 40%) X Yes No						
Garage / Parking / 0	Dutbuildings						
Single garage Available on site?	☐ Double garage ☐ Parking space X No garage / garage space / parking space ☐ Yes ☐ No						
Permanent outbuilding	Permanent outbuildings:						
No permanent outbu	ildings.						

Construction							
Walls	Brick	Stone	Concrete	X Timber frame	Other	(specify in Gen	eral Remarks)
Roof	X Tile	Slate	Asphalt	Felt	_	(specify in Gen	
Special Risks							
Has the property su	ffered structu	ıral movement'	?			Yes	X No
If Yes, is this recent	or progressi	ve?				Yes	No
Is there evidence, h immediate vicinity?	istory, or rea	son to anticipa	te subsidence,	heave, landslip or	r flood in the	Yes	X No
If Yes to any of the	above, provid	le details in Ge	eneral Remarks	5.			
Service Connection	on						
Based on visual inspof the supply in Gen			appear to be	non-mains, please	comment or	n the type ar	nd location
Drainage [X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating [X Yes [Partial	None				
Brief description of 0	Central Heati	ng:					
Heating fuel: Gas							
Heating type: Rad	iators						
, realing types read							
Site							
Apparent legal issue	es to be verif	ed by the conv	eyancer. Pleas	se provide a brief	description in	General Re	emarks.
Rights of way	Shared drive	s / access	Garage or other a	amenities on separate	site Share	ed service conn	ections
Ill-defined boundaries	3	Agricultura	I land included wit	h property	Other	(specify in Ger	neral Remarks)
Location							
Residential suburb	X Resid	dential within town	/ city Mixed	d residential / commerc	cial Mainly	y commercial	
Commuter village	Rem	ote village	Isolat	ed rural property	Other	(specify in Ger	neral Remarks)
Planning Issues							
Has the property been extended / converted / altered? Yes X No							
If Yes provide detail	s in General	Remarks.					
Roads							
X Made up road	Unmade road	Partly cor	npleted new road	Pedestrian ad	cess only	Adopted	Unadopted

General Remarks

The property comprises a first floor flat in purpose built two and three storey block of five flats. The property is situated in a modern residential development in the town of Forres. Surrounding properties are of similar age and character. Usual amenities and transport links are available within a reasonable distance.

Main walls are of conventional timber framed construction with block outer leaf, externally mainly rendered although with part timber cladding. The roof is pitched and tiled.

At the time of inspection the property was found to be in maintained condition with no significant defects.

As the building within which the subject property is located does not, based on our visual inspection, give rise to any specific cause for concern and / or the RICS External Wall System Review Process is not considered to be applicable, based on current RICS guidance, we have assumed that it is free from any / all fire safety defects and is fully compliant with and meets all current building regulation and fire safety standards. However, this decision is not a guarantee that works will not be required in future.

The valuation assumes there is a suitable and enforceable shared maintenance / management agreement for the block and surroundings.

It is assumed that there are local authority consents and certifications along with Premier insurance documentation from Springfield Properties and it is assumed that this documentation will be made available.

Essential Repairs			
None required.			
Estimated cost of essential repairs £	Retention recommended? Yes	X No	Amount £

Comment on Mortgagea	bility	
The property affords adeq lender's criteria.	quate security for loan purposes based on the valuation figure, subject to i	ndividual
Valuations		
Market value in present cor	ndition	£ 130,000
Market value on completion of essential repairs		
Insurance reinstatement value		£ 230,000
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)		
Is a reinspection necessary	?	Yes X No
Buy To Let Cases		
What is the reasonable rangementh Short Assured Tenal	ge of monthly rental income for the property assuming a letting on a 6 ncy basis?	£
Is the property in an area w	here there is a steady demand for rented accommodation of this type?	Yes No
Declaration		
Signed	Security Print Code [585236 = 6881]O Electronically signed by:-	
Surveyor's name	John I Dougan	
Professional qualifications	MRICS	
Company name	Harvey, Donaldson and Gibson	
Address	Duncan House, Wester Inshes Place, Inverness, Highland, IV2 5HZ	
Telephone	01463 718440	
Fax	01463 714732	
Report date	17th August 2023	

Energy Performance Certificate (EPC)

Dwellings

Scotland

28 RIDDOCK GARDENS, FORRES, IV36 2QE

Dwelling type:Mid-floor flatDate of assessment:16 August 2023Date of certificate:16 August 2023

Total floor area: 65 m²

Primary Energy Indicator: 82 kWh/m²/year

Reference number: 0112-2566-5483-2497-8905 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains

gas


You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly

Estimated energy costs for your home for 3 years*

£1,782

 st based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (85)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band B (89)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed) Cavity wall, as built, insulated (assumed)	**** ****	**** ****
Roof	(another dwelling above)	_	_
Floor	(another dwelling below)	_	_
Windows	Fully triple glazed	****	****
Main heating	Boiler and radiators, mains gas	****	****
Main heating controls	Programmer, room thermostat and TRVs	****	****
Secondary heating	None	_	_
Hot water	From main system	****	****
Lighting	Low energy lighting in all fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 14 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 0.9 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

Recommendations Report

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£843 over 3 years	£843 over 3 years	
Hot water	£573 over 3 years	£573 over 3 years	N 1 (P 11
Lighting	£366 over 3 years	£366 over 3 years	Not applicable
Totals	£1,782	£1,782	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

None

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling Impact of loft insulation Impact of cavity wall insulation		Impact of solid wall insulation		
Space heating (kWh per year)	1,323	N/A	N/A	N/A	
Water heating (kWh per year)	1,642				

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. John Dougan Assessor membership number: EES/016099

Company name/trading name: Harvey Donaldson & Gibson Chartered Surveyors

Address: Duncan House Wester Inshes Place

Highland Inverness IV2 5HZ

Phone number: 01463718440

Email address: frances.wilson@hdg.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.



Property Address	38 Riddock Gardens, Forres, Moray, IV36 2QE,
Vendor(s)	Mr Robert Stevenson
Completion Date of Property Questionnaire	
System Ref:	QV178254-2





Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership		
	How long have you owned the property? 6 years 4 months		
2.	Council Tax		
	Which Council Tax band is your property in?		
	A 😵 B 😵 C 🕖 D 😵 E 😵 F 😵 G	6 & H	×
3.	Parking		
	What are the arrangements for parking at your property? Please tick all that apply?		
	Garage ⊗ Allocated parking space ✓	Driveway	8
	Shared parking ⊗ On street ⊗ I	Resident permit	8
	Metered parking 😵 Other (please specify):		
4.	Conservation area		
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	Yes No	
		Don't know	
5.	Listed buildings		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes No	
6.	Alterations/additions/extensions		
a.	During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes No	_
(i)	If you have answered yes, please describe below the changes which you have made:	1	
(ii)	Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes No	&
(iv)	If you have answered yes, the relevant documents will be needed by the purchaser and you s solicitor as soon as possible for checking. If you do not have the documents yourself, please no these documents and your solicitor or estate agent will arrange to obtain them:	hould give them to te below who has	your



6. Alterat	ions/additions/extensions	
b. Have you	had replacement windows, doors, patio doors or double glazing installed in your flyou have answered yes, please answer the three questions below	Yes 😵
D. Property	il you have allowered yes, please allower the times questions below	No 🕢
	ne replacements the same shape and type as the ones you	Yes 😵
(i) replace	d?	No 😵
(ii) Did the	work involve any changes to the window or door openings?	Yes 😵
(11)		No 😵
Please d	escribe the changes made to the windows doors, or patio doors (with approximate date d):	es when the work was
	ive any guarantees which you received for this work to your solicitor or estate agent	
(iii)	ve any guarantees which you received for this work to your solicitor or estate agent	
	I heating	· -
Is there (Note: a	a central heating system in your property? partial central heating system is one which does not heat all the main	Yes 🧭
	f the property — i living room, the bedroom(s), the hall and the bathroom).	No 😵
		Partial 🚷
(Example	<u>ve answered yes or partial</u> – what kind of central heating is there? es: gas-fired, solid fuel, electric storage heating, gas warm air)	
	ntral heating ove answered yes, please answer the three questions below	
		I ::: 1
\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	as your central heating system or partial central heating installed?	with build - 2017
Do you	have a maintenance contract for the central heating system?	Yes 😵
(ii)		No 🕢
lt you ai	<u>iswered yes</u> please give details of the company with whom you have a maintenance co	intract
When w	is your maintenance contract last renewed? (Please provide the month and year)	
(iii)	s your maintenance contract last renewed: (i lease provide the month and year)	
8. Energy	Performance Certificate	
o. Lifery	renonnance centincate	
Does v		Vac 🚺
	our property have an Energy Performance Certificate which is less years old?	Yes ♥
than 10	our property have an Energy Performance Certificate which is less years old?	Yes ♥ No ⊗
than 10	our property have an Energy Performance Certificate which is less years old? that may have affected your property	No 🚷
9. Issues	our property have an Energy Performance Certificate which is less years old?	No ⊗ Yes ⊗
9. Issues Has the propert	that may have affected your property ere been any storm, flood, fire, or other structural damage to your y while you have owned it?	Yes & No 🗸
9. Issues Has the propert	our property have an Energy Performance Certificate which is less years old? that may have affected your property ere been any storm, flood, fire, or other structural damage to your	Yes No Ves S
9. Issues Has the propert	that may have affected your property ere been any storm, flood, fire, or other structural damage to your y while you have owned it? have answered yes is the damage the subject of any outstanding ce claim?	Yes & No Ves & No Ves & No &
9. Issues Has the propert	that may have affected your property ere been any storm, flood, fire, or other structural damage to your y while you have owned it? have answered yes is the damage the subject of any outstanding	Yes & No Ves & No Xes & Yes &
9. Issues a. Has the propert	that may have affected your property ere been any storm, flood, fire, or other structural damage to your y while you have owned it? have answered yes is the damage the subject of any outstanding ce claim?	Yes & No Ves & No Ves & No &



Please tick which services are connected to your property and give c					
Samiles Connected	details of the supplier				
Service	Supplier				
Gas or liquid petroleum gas	Scottish Gas				
Water mains or private water supply	Scottish Water				
a. Electricity	SEB				
Mains drainage ✓ sco	ottish water board				
Telephone	ВТ				
Cable TV or satellite	ВТ				
Broadband	ВТ				
ls there a septic tank at your property?	Yes 😵				
lf you have answered yes please answer the questions below	No 🕢				
Do you have appropriate consents for the discharge of your septic ta	ank? Yes 😵				
(i)	No 😵				
	Don't know 🔕				
Do you have a maintenance contract for your septic tank?	Yes 😵				
(::)	No 🐼				
(ii) <u>If you answered yes</u> please give details of the company with whom you have a maint	If you answered yes please give details of the company with whom you have a maintenance contract				
11. Responsibilities for shared or common areas					
Are you aware of any responsibility to contribute to the cost of anything used jointly, such as repair of a shared drive, private road, boundary					
garden area?	No 🚫				
a.	Don't know 🚫				
	Bont know &				
If you answered yes please give details	DOIT KNOW W				
Fees of approx 30 GBP/month for power and cleaning of communal sta					
Fees of approx 30 GBP/month for power and cleaning of communal sta landscaping charges for shared outside areas	irwell and maintenance and				
Fees of approx 30 GBP/month for power and cleaning of communal sta	irwell and maintenance and				
Fees of approx 30 GBP/month for power and cleaning of communal stalandscaping charges for shared outside areas Are you aware of any responsibility to contribute to the cost of repair maintenance of the roof, common stairwell, or other common areas?	and Yes No 😣				
Fees of approx 30 GBP/month for power and cleaning of communal stalandscaping charges for shared outside areas Are you aware of any responsibility to contribute to the cost of repair maintenance of the roof, common stairwell, or other common areas? b.	irwell and maintenance and				
Fees of approx 30 GBP/month for power and cleaning of communal stalandscaping charges for shared outside areas Are you aware of any responsibility to contribute to the cost of repair maintenance of the roof, common stairwell, or other common areas?	and Yes No 😣				
Fees of approx 30 GBP/month for power and cleaning of communal stalandscaping charges for shared outside areas Are you aware of any responsibility to contribute to the cost of repair maintenance of the roof, common stairwell, or other common areas? b. If you answered yes please give details	and Yes No No Don't know				
Fees of approx 30 GBP/month for power and cleaning of communal stalandscaping charges for shared outside areas Are you aware of any responsibility to contribute to the cost of repair maintenance of the roof, common stairwell, or other common areas? b. If you answered yes please give details Yes	and Yes No No Don't know				
Fees of approx 30 GBP/month for power and cleaning of communal stalandscaping charges for shared outside areas Are you aware of any responsibility to contribute to the cost of repair maintenance of the roof, common stairwell, or other common areas? b. If you answered yes please give details Yes Has there been any major repair or replacement of any part of the roof.	irwell and maintenance and Yes No Don't know No				
Fees of approx 30 GBP/month for power and cleaning of communal stallandscaping charges for shared outside areas Are you aware of any responsibility to contribute to the cost of repair maintenance of the roof, common stairwell, or other common areas? b. If you answered yes please give details Yes Has there been any major repair or replacement of any part of the roduring the time you have owned the building? Do you have the right to walk over any of your neighbours' property, example to put out your bins, or to maintain your boundaries?	and Yes Voor No Solor Yes No				
Fees of approx 30 GBP/month for power and cleaning of communal stallandscaping charges for shared outside areas Are you aware of any responsibility to contribute to the cost of repair maintenance of the roof, common stairwell, or other common areas? b. If you answered yes please give details Yes Has there been any major repair or replacement of any part of the roduring the time you have owned the building? Do you have the right to walk over any of your neighbours' property,	irwell and maintenance and Yes No Don't know oof Yes No oof No o				



11.	Responsibilities for shared or common areas			
	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin, or to maintain their boundaries?	Yes 😵		
e.	property, for example to put out their rubbish biri, or to maintain their boundaries?	No 🤡		
C.	<u>If you answered yes</u> please give details			
		,		
	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.)	Yes 😵		
f.		No 🔗		
	<u>If you answered yes</u> please give details			
12.	Charges associated with your property			
12.	Is there a factor or property manager for your property?	Yes 🗸		
	To those a laster or property manager to your property.	No 😣		
a.	If you answered yes please provide name and address and give details relating to deposits held			
	Screen Autumn - subsidiary of Springfield			
	Is there a common buildings insurance policy?	Yes 🗸		
		No 🐼		
b.		Don't know 🚫		
	If you answered yes is the cost of insurance included in your monthly/annual factor's charges?	Yes		
	Yes	No		
	Please give details of any other charges you have to pay on a regular basis for the upkeep of common			
C.	areas or repair works, for example to a residents' association, or maintenance or stair n/a	iulia.		
13.	Specialist works			
	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes 😵		
		No 🔗		
	If you answered yes please give further details			
a.	Da von have and suggestion for this word?			
	Do you have any guarantees for this work?	Yes 😵		
	Guarantees are held by :	No 😵		
	As far as you are aware, has any preventative work for dry rot, wet rot, or damp	Yes 😵		
	ever been carried out to your property?	No 🐼		
	If you answered yes please give further details	110		
b.	, 3			
	Do you have any guarantees for this work?	Yes 😵		
		No 😵		
	Guarantees are held by :	,		



14.	Guarantees					
	Are there any warranties or guarantees for any of the following					
a.		No	Yes	Don't know	With title deeds	Lost
(i) b.	Electrical work	8	8	Ø	8	8
(ii) b.	Roofing	8	8	Ø	8	8
(iii) b.	Central heating	8	8	Ø	8	8
(iv) b.	National House Building Council (NHBC)	8	8	Ø	8	8
(v) b.	Damp course	8	8	Ø	8	8
(vi)	Any other work or installation? (for example cavity wall insulation, underpinning, indemnity policy)	×	×		×	×
b.		<u>I</u>				
	Are there any outstanding claims under any of the guarantees listed ab	ove?				es 😵 No 🧭
c.	<u>If you answered yes</u> please give details					,
15.	Boundaries					
	Are you aware has any boundary of your property been moved ten years?	in the I	ast			es 😵 No 🧭
a.				Do	n't kno	w 😵
	<u>If you answered yes</u> please give details					



16.	Notices that affect your property			
	In the past three years have you ever receievd a notice :			
a.	Advising that the owner of a neighbouring property has made a planning application?	Yes ⊗ No ⊘		
b.	that affects your property in some other way?	Yes No 🥥		
c.	that requires you to perform any maintenance, repairs, or improvements to the property?	Yes ⊗ No ⊘		
	If you answered yes to any of a-c above please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property			

Declaration by the seller(s) or other authorised body or person(s)

I/We confirm that the information on this form is true and correct to the best of my/our knowledge and belief.

Signatures:

Robert Stevenson

Date:



